

MCM DTC 521133/13 – DPF Ash Mileage

COMMUNICATION:

FIELD SOLUTION: *Troubleshooting Manual to be updated*

PUBLISH DATE: TBD/2026

TOPIC BACKGROUND:


PRIMARY EFFECT:

- Code 521133/13 – ACM Reported Ash Mileage is Lower than MCM Stored Value may log falsely in the MCM due to signal noise.

AFFECTED MODELS:

- CY22-23 DD13 with GATS2.0
- CY24 DD13 with GATS2.4
- CY21-24 DD15 with GATS2.0
- CY22-24 DD16 with GATS2.0

VISUALIZATION:



PROGRESS UPDATES:

- February 2026: SW release complete for CY21-24 DD15 and CY23 DD13.
- DL8.24 planned to include an ash adjustment panel in ~May 2026.
- Troubleshooting to be updated with software levels required for correction.

TOPIC RESOLUTION INFORMATION:

PRODUCTION CHANGEOVER WEEK/MONTH:

- Production Change Over: January 2025 for DD13, DD15 with GATS2.4 and DD16.

RESOLUTION:

- New software was released in 2025 that contained a change to improve the ash calculation.
- An additional software update is now available for units that were previously stranded due to production changeovers.

