

# SS 308 TBB Timer relay TBB 202400 replacement

## Applicable Vehicles

2023 and newer HDX2/ EFX2/ HDX/EFX

## Issue

Discontinued TBB 202400 Timer relay

## Solution

Replace with TBB 251008, adding Battery power per TBB241528 (**rev B**) to pin 87A on the relay.  
Diagram can be found on TBB ESP Parts Inquiry

Labels :

Saf-T-Liner

Add tags



0 Kudos

Comment