

L634-
A.06.26

To: After Sales Official Network
Subject: Steering wheel replacement
Date: 05/03/2026
Pages: 3



Campaign code:
L634-A.06.26

Campaign name:
Steering wheel replacement

Model:
Temerario

Model Year:
2026

Markets:
France, United States, United Kingdom, South Africa

VIN Involved:

ZHWEC1ZC5TLA00931, ZHWUC1ZC4TLA00947,
ZHWEC1ZC0TLA00948, ZHWEC1ZC7TLA00963


Important information: before proceeding with the repair, connect to the Warranty Portal and, using the “VIN Info” function, check that:

- the vehicle is actually affected by the instructions contained in this bulletin.

NOTE: some vehicles may not be affected, despite the fact that their Vehicle Identification Number (VIN) falls within the range;

- only replacement parts that correspond to the specific operation, identified by a letter (such as A, B, C, etc.), are to be used for the chassis being repaired.

Example



NOTE:

Operation A will be available only when the instructions require a preliminary check to be performed to determine whether or not the vehicle actually needs updating.

Information for the service network:

During ongoing product monitoring, Automobili Lamborghini S.p.A. noted that some Steering Wheels may have rotary switches remain stuck in half position after release

Solution for the field:

Replace Steering Wheel

Spare Parts:

OPERATION B (For ZHWEC1ZC5TLA00931)

Part number	Description	Q.ty
4LA419091A	STEERING WHEEL	1

OPERATION C (For ZHWUC1ZC4TLA00947, ZHWEC1ZC0TLA00948)

Part number	Description	Q.ty
4LA419091B	STEERING WHEEL	1

OPERATION D (For ZHWEC1ZC7TLA00963)

Part number	Description	Q.ty
4LA419091C	STEERING WHEEL	1

Management of replaced parts:

Store the components that have been removed from the vehicle in an appropriate manner, marking them with their corresponding bar codes so that they can be identified during visits by the competent Area Manager.

Rev.00

The procedures and information published herein are strictly confidential and are intended exclusively for recognized professionals and persons who are authorized to receive said information. All copyrights are the property of Automobili Lamborghini S.p.A pursuant to copyright law. The company reserves the right to make updates and modifications as needed. The reprinting, reproduction, distribution to unauthorized persons and/or to third parties, and the partial or complete translation of the material contained herein are prohibited without the express written consent of Automobili Lamborghini S.p.A.

Doc. no.: L/V6_M06 Rev.[07]

1/3



Labor time:


Operation B: 1.1h
Operation C: 1.1h
Operation D: 1.1h

Previous bulletins superseded.

None.

Warranty claim instructions:

To request reimbursement for the repair performed, access the “LIASS” system on the Lamborghini portal and, following the instructions in the system’s “Manuals” section, generate and fill out a Warranty Request. Select the required campaign and proceed with entry; carefully read the options present in the alert message that displayed by the system (see example) and select the option performed on the vehicle.



Reimbursement will be structured as follows, on the basis of the operation performed:

- **OPERATION B:**
 - o Steps to be executed: 1
 - o Labour time: 1.1 h
- **OPERATION C:**
 - o Steps to be executed: 1
 - o Labour time: 1.1 h
- **OPERATION D:**
 - o Steps to be executed: 1
 - o Labour time: 1.1 h

Important information:

attach all documents generated during the work carried out, evidence of the work itself, for instance work orders and diagnostic protocols with BETA-Reports.

If one or more of these is missing, it may lead to a rejected reimbursement request.

Fill out the page in the warranty booklet (identified in the image below) in the section “Service and Recall Campaigns”:

Tools/Materials required:

Code	Description.	Q.ty
n/a	n/a	n/a



NOTE:

All O.D.I.S. Service technical documentation can be viewed on the app “O.D.I.S. Self Service Guide” available on Lamborghini HUB portal.



Repair method:
OPERATION B (For ZHWEC1ZC5TLA00931)

Follow the instructions given in the Workshop Manual at the following path:

1. Steering Wheel - Replacement procedure
Steering > Front Steering > Steering wheel > Replacement procedure

Once the order for the steering wheel has been placed, please open a ticket in Lamborghini Key with the following qualification layer the Order nr:

Lamborghini Key Request/General Information - After Sales Spare Parts - Back office – ZMTO

OPERATION C (For ZHWUC1ZC4TLA00947, ZHWEC1ZC0TLA00948)

Follow the instructions given in the Workshop Manual at the following path:

1. Steering Wheel - Replacement procedure

Steering > Front Steering > Steering wheel > Replacement procedure

Once the order for the steering wheel has been placed, please open a ticket in Lamborghini Key with the following qualification layer the Order nr:

Lamborghini Key Request/General Information - After Sales Spare Parts - Back office – ZMTO

OPERATION D (For ZHWEC1ZC7TLA00963)

F Follow the instructions given in the Workshop Manual at the following path:

1. Steering Wheel - Replacement procedure

Steering > Front Steering > Steering wheel > Replacement procedure

Once the order for the steering wheel has been placed, please open a ticket in Lamborghini Key with the following qualification layer the Order nr:

Lamborghini Key Request/General Information - After Sales Spare Parts - Back office – ZMTO



IMPORTANT:

The documents which must be provided together with the operation under warranty request are:

- Produced Repair Order
- Saved Diagnostic Protocol with BETA report

Failure to follow these procedures could lead to the request being rejected.

For more information, please contact your Area Manager or open a ticket to Technical Support in Lamborghini KEY (Request – General Information – After Sales Services - After Sales Technical Support).

Regards,
Lamborghini Service