

SSM76306-DTC's STORED WITHIN THE PCM – MID CATALYST HO2S - 4.4L

- Range Rover**
- 22-23MY Range Rover
 - 23MY RR Sport

Customer Voice:

- "There is a MIL light on my dash.."

Status:

- This concern is currently under investigation.

Action – Service Request:

- The following DTCs will be stored in PCM or PCMB:
 - P2270-00 O2 Sensor Signal Biased/Stuck Lean Bank 1 Sensor 2
 - P2272-00 O2 Sensor Signal Biased/Stuck Lean Bank 2 Sensor 2
- If one or more of these listed DTC's are present in the PCM, please replace the applicable sensor.
- Please raise an EPQR and please reference SSM76306 with all the relevant information.
- Do not discard the removed part(s), it will be required for parts return request which will be arranged by relevant JLR engineering team.

