

Outside Mirrors Do Not Fold In When Locking With Radio Remote Control

| | |
|-------------------|----------------------------------|
| Topic number | LI88.70-P-080030 |
| Version | 1 |
| Function group | 88.70 - Exterior mirrors |
| Date | 4/8/26 |
| Validity | TYPE 463 (as of model year 2018) |
| Reason for change | |

Complaint

The outside mirrors do not fold in when locking with the radio remote control, even though the function is activated in the vehicle settings.

Folding and unfolding still functions via pushbutton switch on the door.

Cause

The initialization data for the outside mirrors is lost in the door control unit.

Remedy

Replacing the control unit provides no remedy.

The initialization data in the control unit is restored by manually folding in the outside mirrors using the pushbutton switch in the door.

After that, the function is restored when locking with the radio remote control.

However, under certain circumstances, this data could be lost again.

In this case, this procedure would have to be repeated.

Disclaimer

NOTE: The information contained in this document is intended for use by trained, professional technicians with the knowledge to properly and safely perform diagnosis and repairs on Mercedes-Benz vehicles, using Mercedes-Benz approved tools and equipment. It informs service technicians about conditions that could occur in certain vehicles and provides information that could assist in proper vehicle diagnosis, service, or repair. It does not indicate that a defect is present in any vehicle referenced in this document nor does it imply warranty coverage. DO NOT assume that a symptom or condition, or a described cause of a symptom or condition, affects any particular vehicle or groups of vehicles, or that a described repair applies to any particular vehicle or groups of vehicles. There can be multiple causes resulting in the same or similar symptoms or conditions described in this document, and trained professional service technicians must use their diagnostic skills to make evaluations on a case-by-case basis. The information contained in this document does not guarantee warranty coverage nor does it extend the vehicle's warranty in any way.

XENTRY Tips

| |
|--|
| Symptoms |
| Overall vehicle > Safety and locking system > Comfort opening/closing system > Malfunction |
| Body > Door/Flap > Outside mirror > Mirror/Mirror adjustment > Operation malfunction |
| Body > Door/Flap > Outside mirror > Power folding mirrors > Malfunction |

| Operation numbers/damage codes | | | | |
|--------------------------------|----------------|------|-------------|-------------------------|
| Op. no. | Operation text | Time | Damage code | Note |
| | | H | 81P0151 | Left-hand side: 81B0151 |