



Date:
30.04.2026

Affected Models:
All Emira Models

Affected Regions:
All regions

Affected Volume:
N/A

Number:
131-26009

Copy files should be maintained by:

Service Manager		Service Reception		Supervisor		Parts Manager	
-----------------	--	-------------------	--	------------	--	---------------	--

TITLE


Availability of ASO exhaust muffler (rear silencer) valve actuator as service replacement part.

REASON

Until recently the failure of the exhaust muffler valve actuator has required the exhaust muffler and valve to be renewed as a complete assembly.

The exhaust muffler valve actuator is now available as a separate replacement part. The advantages of not having to replace the combined assembly are for a faulty actuator are:

- Less labour-intensive procedure to replace.
- More practical to keep an exhaust muffler valve actuator as a parts stock item.



Part number	Description	Qty/vehicle
8902858596	ASO Exhaust Muffler Valve Actuator	1

Part number also shown in the Emira EPC, available to view in TIS: section 1. Power > 12 Induction and Exhaust System > 118.45.01 Exhaust System.

ACTION

If an exhaust muffler valve actuator is diagnosed as faulty then please determine if the exhaust flow valve mechanism in the rear silencer is operating and moving correctly*, if it is then please fit a new valve actuator instead of a complete muffler assembly.

*Actuator replacement is only suitable if the exhaust flow valve mechanism in the rear silencer is operating and moving correctly. If the exhaust flow valve is not operating or seized, then the exhaust silencer or actuator assembly should be replaced.

Full information for removing and replacing the exhaust muffler valve actuator are shown in the Emira Service Notes available to view in TIS: section 1. Power > 12 Induction and Exhaust System > 118.45.01 Exhaust System > Valve Actuator – V6 or 4 – Cylinder Replacement.

CHARGES

No charges are associated with the contents of this bulletin.

Ends.