

## GPOP - Issue Review System

**Part Number:** 68293288A\$, 68293289A\$

**Part Description:** RH cylinder head

**Issue Description:** Camshaft cap bolts within the cylinder head assembly may cause damage to other components. DO NOT replace entire long block when only left OR right cylinder heads need to be replaced.