



## **SSM 54747 2025-2026 Ranger - 12 Inch IPC Display Screen - IPC Backlight and Shift Indicator Remains Illuminated After The Vehicle Is Turned Off**

Some 2025-2026 Ranger vehicles equipped with a 12-inch instrument panel cluster (IPC) display may exhibit a condition where the IPC backlight and shift indicator remains illuminated after the vehicle is turned off. This may be due to the software in the IPC. To correct the condition, using the latest software level of the Ford Diagnosis and Repair System (FDRS) scan tool, download and run the "IPC - Instrument Panel Cluster (IPC) Software Update" application. For claiming, use causal part 10849 and labor operations 12651D and 12651D4.