

2021-2024 MY Edge

Accessory Protocol Interface Module - SYNC

SYNC-26.2.0.16.2

Safety Recall 26S09

Accessory Protocol Interface Module

To view your past software updates, or if you've had multiple updates completed recently, visit: <https://www.ford.com/support/software-updates>

1

SYNC-26.2.0.16.2

"This software update contains the following key changes:

- On your vehicle, it may be possible to experience an unexpected blank infotainment screen due to the APIM (Accessory Protocol Interface Module) temporarily shutting down when detecting high temperatures. When the APIM shutdown occurs, your vehicle can no longer display the rearview camera image while in reverse. A rearview camera image that does not display while in reverse gear can reduce your view of what is behind the vehicle, increasing the risk of a crash. We have updated your APIM to correct this condition. This completes Safety Recall 26S09. No further action is required."