



# IMPORTANT SAFETY RECALL

This notice applies to your vehicle. Refer to the provided list.

NHTSA Safety, FMVSS Compliance, or Emissions Recall

Dear Altec Owner,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act and the Canada Motor Vehicle Safety Act.

Altec Industries, Inc. has received notification from an Original Equipment Manufacturer (OEM) that a condition exists relating to motor vehicle safety, compliance, or emissions in a vehicle you possess that is equipped with Altec equipment.

Refer to the attached documentation that follows this letter. If you have additional questions, please contact your Altec Account Manager. You may also contact the OEM using the contact information provided in the attached recall notice.

For US owners: after contacting the OEM according to the attached notice, if you are still not able to have the safety condition remedied within a reasonable time, you may write to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington, DC 20590 or call 1-888-327-4236 (TTY: 1-800-424-9153) or go to <http://www.safercar.gov>.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you have sold or retired the unit, update the records through Altec Connect. If you have leased this equipment to another person or company, you are required by Federal Law to forward a copy of this notice to the lessee by first class mail within ten (10) days of the receipt of this notice.

We appreciate your assistance in following this action in the interest of your continued satisfaction with Altec products.

Thank you for your immediate attention on this important matter.



# COMPONENT/SUPPLIER RECALL CSR-3289-A

## Brake Pressure Switch Safety Recall (International 25507 — NHTSA 25V414)

**Units Affected:** 2019-2025 CV® Series trucks built 1/11/2018 thru 9/9/2024, with feature codes 0004198, 0004240 (brake system, hydraulic with Hydromax brake booster). Verify your unit is affected by reviewing the attached list or accessing Altec Connect.

**Background:** Altec is committed to providing our customers reliable products from initial delivery throughout the useful life of the machine.

International Motors has decided a defect which relates to motor vehicle safety exists in your vehicle with the VIN shown in the attached list.

Refer to the included communication from International Motors for more information.

**Customer Action:** Follow the guidance in the included communication from International Motors.

**Requirements:** Altec is not able to perform this repair.

**Completion and Warranty:** This repair is not covered under the Altec Warranty Policy.

**Altec Contact Info:**

Phone: 1-877-GO ALTEC (1-877-462-5832) — Altec Connect Customer Portal: [altec.com/altec-connect/](https://altec.com/altec-connect/)

Altec Use Only	
Inspection labor	N/A
Repair labor	N/A
Account #	N/A
Travel	Not included
NHTSA code	90
Prime fail P/N	N/A
Kit instructions	N/A

Altec Use Only			
Description	Part No.	Qty	Warranty
N/A	N/A	N/A	N/A

August 2025

**IMPORTANT SAFETY RECALL 25507**

Interim Notice

NHTSA RECALL NO. 25V414

This notice applies to your vehicle identified on the enclosed card.

Dear International Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

International Motors, LLC has decided that a defect which relates to motor vehicle safety exists in certain 2019 thru 2025 CV® Series trucks built 1/11/2018 thru 9/9/2024, with feature codes 0004198, 0004240 (Brake system, hydraulic with Hydromax brake booster).

**REASON FOR THIS RECALL**

The brake pressure switch may allow brake fluid to seep past the diaphragm seal into the brake pressure switch electrical connector and associated fuse which can short the switch and/or fuse.

**RISK TO MOTOR VEHICLE SAFETY**

A shorted switch or fuse may cause the circuit to generate excessive heat which can result in a fire, increasing the risk of property damage or personal injury to the operator.

**IF YOU NEED FURTHER ASSISTANCE**

Refer to the Owner Assistance Guide section in your Owner's Manual or call toll free 1-800-448-7825. International Motors, LLC requests your prompt attention and patience regarding the correction of this defect and apologizes for any inconvenience this may cause you.

**DEFECT REMEDY***You may already have been contacted about a similar Safety Recall 23511 (NHTSA 23V-282) in June of 2023. Any vehicle remedied under that recall also requires this recall remedy to be performed.*

A final remedy has been determined. Parts are on order, but availability is currently unknown. A second notice will be sent to you, once the free remedy is available.

**ACTIONS YOU SHOULD TAKE****Until the remedy can be performed, vehicle owners are advised to park their vehicles outdoors.**

If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within ten days to comply with federal regulations.

If you do not own this vehicle, please fill out and return mail the enclosed card so that you will not be contacted again about this recall.