

 Preview Solution CBR-2362-3

Mack - Carrier Nut Adhesive Change - Part Number 22952162

Published 9 April 2025


Valid For

All models, model year 2008 to present


Solution

Due to a change in the type of adhesive used to secure the rear input nut on Mack drive axles, **a new cure time MUST BE observed when replacing the nut.** See below for more information.


This solution concerns part number 22952162, shown in the diagram below.



The current adhesive which is blue in color, is being discontinued. Due to this, the adhesive used to secure the carrier nut has been changed to a yellow-colored product. Examples of both are shown below.



Old Part



New Part

The yellow adhesive has a MINIMUM cure time of FOUR HOURS.

A minimum of 4 hours should be allotted following replacement with a part that uses the yellow adhesive before the vehicle is test driven or returned to service in order for the adhesive to properly cure.

If necessary, the vehicle may be moved a short distance from the service bay when repairs are completed and parked for the duration of the cure time.

A part supercession will be implemented in the future, but the part number for both old and new parts is currently the same.

Related links and attachments

No links or attachments available



Share

to others that might find it helpful



Feedback

[Give feedback](#)

to help improve the content of this article