

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
A3, S3, and RS3	2025 – 2026	All	With PR: GP1 (Vehicles with special upgrade measures) -and- With PR: 4A3 (Seat heater for front seats separately controlled)

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised <i>Condition</i> (Change to text) Revised <i>Production Solution</i> (Change to text)
2	12/01/2025	Revised header (PR code filter correction) Revised <i>Condition</i> (Change to text, added model table) Revised <i>Production Solution</i> (Change to text) Revised <i>Service</i> (Change to text, revised technical solution date)
1	04/14/2025	Initial publication

Customer states:

- The customer complains that the seat heater button on the air conditioner control flashes intermittently. The seat heating function is unavailable while the button is flashing.

Workshop findings:

- The complaint can be reproduced in the workshop. No event memory entries are logged in diagnostic address 0008. The issue in the vehicle can be remedied by pressing the button again or switching the ignition off and on again.

Technical Background

Software issue in control unit for air conditioner and heater electronics.

Production Solution

Production change with software 5067 (diagnostic address 0008) in week 25/2024.

Service

1. Explain to the customer that a technical measure is currently being analyzed. This analysis is expected to be completed by the end of the second quarter of 2026 (subject to change) and no repairs are necessary at this point.
2. Do not replace any components for this condition since this will not resolve the customer's concern.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in Audi Now; *Service | AU-US > Pending Service Solutions (PSS)*.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2077639**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.