

# 45-070: Cummins X15 Dust Intrusion Inspection

4/15/2026

 [Edit](#)  [Clone](#)

45-070

Cummins X15 Dust Intrusion Inspection

## Subject

---

Cummins X15 Dust Intrusion Inspection

## Whats New Abstract

---

The attached procedures document has been updated with more detail and explanations. This is not a stand-alone procedure. Cummins Quickserve troubleshooting will specify the use of these procedures while troubleshooting specific fault codes.

## Revision

---

4/45/2026: Bulletin procedures updated.

1/30/2026: Procedure pictures updated for clarity.

## Condition

---

Any Cummins X15 engine with active fault codes 555 or 556 is affected. Cummins fault code troubleshooting will refer to this bulletin and procedure. These procedures are to be performed ONLY as part of Cummins troubleshooting.

## Chassis Affected

---

Any MY2017 or later Kenworth Heavy Duty chassis with a Cummins X15 engine with active fault codes 555 or 556.

## Action

---

### **Info Only**

This procedure should only be performed when directed by Cummins QuickServe troubleshooting for fault

codes 555 or 556.

## Procedure

---

**Please follow your dealership's safety procedures and precautions to ensure the vehicle can be safely repaired and maintained. Read all steps before beginning.**

## Attachments

---

[Procedure](#)

[Torque Value Record Sheet](#)

---

Authored by: JB3

# 45-070: Cummins X15 Dust Intrusion Inspection

4/15/2026

 [Edit](#)  [Clone](#)

45-070

Cummins X15 Dust Intrusion Inspection

## Subject

---

Cummins X15 Dust Intrusion Inspection

## Whats New Abstract

---

The attached procedures document has been updated with more detail and explanations. This is not a stand-alone procedure. Cummins Quickserve troubleshooting will specify the use of these procedures while troubleshooting specific fault codes.

## Revision

---

4/15/2026: Bulletin procedures updated.

1/30/2026: Procedure pictures updated for clarity.

## Condition

---

Any Cummins X15 engine with active fault codes 555 or 556 is affected. Cummins fault code troubleshooting will refer to this bulletin and procedure. These procedures are to be performed **ONLY** as part of Cummins troubleshooting.

## Chassis Affected

---

Any MY2017 or later Peterbilt Heavy Duty chassis with a Cummins X15 engine with active fault codes 555 or 556.

## Action

---

### **Info Only**

This procedure should only be performed when directed by Cummins QuickServe troubleshooting for fault

codes 555 or 556.

## Procedure

---

**Please follow your dealership's safety procedures and precautions to ensure the vehicle can be safely repaired and maintained. Read all steps before beginning.**

## Attachments

---

[Procedure](#)

[Torque Value Record Sheet](#)

---

Authored by: JB3