

Technical Service Bulletin (TSB)
B Pillar Applique Rubber Molding Peeling Off

REFERENCE:	TSB: 23-013-26 GROUP: 23 - Body	Date:	April 29, 2026	REVISION:	—
VEHICLES AFFECTED:	2025 - 2026 (M6) Jeep Compass This bulletin applies to vehicles built on or after February 01, 2026 (MDH 0201XX) and on or before April 06, 2026 (MDH 0406XX).	MARKET APPLICABILITY:			
		<input type="checkbox"/> NA <input type="checkbox"/> CH <input type="checkbox"/> EE <input checked="" type="checkbox"/> IAP <input type="checkbox"/> SA <input type="checkbox"/> MEA NOTE: This bulletin applies to India & Asia Pacific markets.			
CUSTOMER SYMPTOM:	Customers may comment on the following: <ul style="list-style-type: none"> Both rear door B Pillar applique rubber moldings are loose Fig. 1. 				
CAUSE:	Loss of bonding				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 26-075, date of issue April 29, 2026. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.



Fig. 1
B Pillar Applique - Rubber Molding Loose

REPAIR SUMMARY:

This bulletin involves replacing both rear door B Pillar appliques.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
23-05-11-9E	B Pillar Applique - Replace (Both Rear Doors) (0 - Introduction)	6 - Electrical and Body Systems	0.4 Hrs.
Failure Code	ZY	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1	Mopar - 68246270AC EMEA - 00534400560E	Applique, B Pillar, Rear	Right Side
1	Mopar - 68246271AC EMEA - 00534400570E	Applique, B Pillar, Rear	Left Side

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. **This RSU only applies to vehicles on the RSU VIN list.**

REPAIR PROCEDURE:

1. Replace both rear door B Pillar appliques. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info> 23 - Body / Doors - Rear / Channel, Door Glass, Rear / Removal and Installation.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.