

# Rotational Clicking Noise From Front Drive Shaft Assembly on Acceleration

**Service Category** Drivetrain

**Section** Drive Shaft/Propeller Shaft

**Market** USA

Toyota Supports  
ASE Certification 

## Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2024	Grand Highlander, Grand Highlander HV	

### **OBSOLETE NOTICE**

April 17, 2026: This bulletin is now obsolete. Please see [T-SB-0028-26](#).