



Service Bulletin

Bulletin No.: PIT6515

Date: May, 2026

PRELIMINARY INFORMATION

Subject: Right Mirror Camera Inoperative In Forward View With Surround Vision

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
GMC	Yukon	2025 - 2026		All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	5SA, UV2 w/o DRZ
Condition	A customer may comment the Right side 360 camera doesn't function properly but only when viewing forward view. 360 and rear view of the same camera functions normal.
Cause	The cause of the condition may be software anomalies.

Correction

Do not replace any parts.

Engineering is currently investigating.

In the meantime please continue to drive your vehicle.

The PI will be updated or replaced with TSB once a determination has been made.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
*3481548	Verify Surround View Camera Concerns	0.2 Hr.
*This is a unique Labor Operation for Bulletin use only.		

Version	1
Modified	05/4/2026 Created On

