

## Detachment of the Maybach Emblem at the C-pillar


---

Topic number	LI88.85-P-080644
Version	1
Function group	88.85 - Trim strips
Date	5/26/26
Validity	Model series 223.9 with code 5B2, without code PMA, up to production date July 28, 2025
Reason for change	

---

### Complaint

The Maybach emblem at the C-pillar is detached from the vehicle

Attachments	
File	Description
Bild1.jpg	Detachment of the Maybach emblem at the C-pillar
	

### Cause

The adhesive bond has failed

### Remedy

The adhesive has been optimized.

Perform replacement of the Maybach emblem on both sides of the vehicle.

Note:

# XENTRY Tips

The old part numbers include the updated adhesive and may be used if the newer parts are not available.

WIS-References		
Document number	Title	Note
AR88.40-P-4051S	Remove/install the Maybach emblem	Replace on both sides

## Disclaimer

NOTE: The information contained in this document is intended for use by trained, professional technicians with the knowledge to properly and safely perform diagnosis and repairs on Mercedes-Benz vehicles, using Mercedes-Benz approved tools and equipment. It informs service technicians about conditions that could occur in certain vehicles and provides information that could assist in proper vehicle diagnosis, service, or repair. It does not indicate that a defect is present in any vehicle referenced in this document nor does it imply warranty coverage. DO NOT assume that a symptom or condition, or a described cause of a symptom or condition, affects any particular vehicle or groups of vehicles, or that a described repair applies to any particular vehicle or groups of vehicles. There can be multiple causes resulting in the same or similar symptoms or conditions described in this document, and trained professional service technicians must use their diagnostic skills to make evaluations on a case-by-case basis. The information contained in this document does not guarantee warranty coverage nor does it extend the vehicle's warranty in any way.

Symptoms
Body > Body/Cab > Trim strip/cover > Detaches
Body > Body/Cab > Trim strip/cover > Damaged
Body > Body/Cab > Trim strip/cover > Missing

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A0059891971			Cleaner	as needed	Sufficient for multiple vehicles	X
A2238170200			Symbol sign, left	as needed	Old part number	X
A2238172800			Symbol sign, right	as needed	Old part number	X
A2238172901			Symbol sign, left	1	New part number	X
A2238173001			Symbol sign, right	1	New item number	X

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
		H	81D03K8	Model badge on left C-pillar – detachment
		H	81S03K8	Model badge on right C-pillar – detachment