



INFINITI®

CAMPAIGN BULLETIN

Spare Tire Label

Campaign ID: PD195

Date: April 30, 2026

Attention: Retailer Principal, Sales, Parts and Service Managers

Affected Models/Years:	Affected Population:	New Retailer Inventory:	SERVICE COMM Activation date:
2026 QX60 (L51)	NA	2	April 30, 2026

***** Retailer Announcement *****

To ensure continued client satisfaction and confidence, INFINITI is conducting a Retailer Quality Action on certain model year 2026 INFINITI QX60 vehicles identified in Service Comm and DBS National Service History.

Condition:

On certain vehicles, a French-Canadian spare tire instruction label may have been incorrectly installed instead of a U.S. Federal label.

Remedy:

INFINITI retailers will install the correct label.

***** What Retailers Should Do *****

PLEASE FOLLOW THE ATTACHED REPAIR INSTRUCTIONS:

1. Verify if vehicles are affected by this quality action using Service Comm or DBS National Service History – Open Campaign I.D. **PD195**
 - New vehicles in retailer inventory can also be identified by using DBS (Sales-> Vehicle Inventory, and filter by Open Campaign).
 - Refer to IPSB 15-286 for additional information
 - Some vehicles may still be in transit. Please continue to check newly arriving inventory for QA applicability.
2. Use the attached procedure to remedy any vehicles affected by this quality action prior to sale.
3. Once remedied, retailers should submit the claim using the claims coding provided and release the vehicle.

***** Retailer Responsibility *****

It is the retailer's responsibility to check Service Comm or DBS National Service History – Open Campaign using the appropriate campaign I.D for the inspection status on each affected vehicle currently in new vehicle inventory.



PD195 – 2026 QX60 SPARE TIRE CAUTION LABEL

Release Date: 04/30/26

Version #1

REPAIR PROCEDURE:

- 1. Place the vehicle on a suitable lift and raise it up.



Figure 1

- 2. Locate the spare tire at the rear of the vehicle.



Figure 2

3. Using a clean rag, wipe the spare tire rim area shown in Figures 3 and 4 with isopropyl alcohol.

- Allow the area to completely dry before moving to Step 4.




Figure 3



Figure 4

4. Apply the Caution Label to the spare tire steel rim.

- Obtain the Caution label shown in Figure 5 (See Parts Information)
- Peel the label from the backing (Figure 6)
- Affix the label to the steel rim to the area shown in Figure 7




Figure 5



Figure 6



Figure 7

5. Lower the vehicle and remove from the lift.

PARTS INFORMATION:

Part Number	Description:	Qty
40353-40U05	CAUTION LABEL	1

CLAIMS INFORMATION:

Submit a "CM" line claim using the following claims coding:

Campaign ("CM") ID	Description:	Op Code	FRT
PD195	Add Spare Tire Caution Label	PD1950	0.2 Hr

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
April 30, 2026		Original bulletin published