

Bulletin #: C32-0526-0630		<input type="checkbox"/> Take Note	<input checked="" type="checkbox"/> Take Action
<input type="checkbox"/> Retail Operator	<input type="checkbox"/> Sales Pre-Owned	<input type="checkbox"/> Business Manager	<input checked="" type="checkbox"/> Parts & Accessories
<input type="checkbox"/> General Manager	<input type="checkbox"/> Sales New Car	<input type="checkbox"/> Service	<input type="checkbox"/> Administration
Name:		Phone Number:	
Title:		Source: Parts Logistics	
Date: May 04, 2026		Supersedes:	



BMW PARTS BULLETIN

TEC857 STARTER RETURN

TAKE ACTION

BMW AG has requested the inspection and return of the following part number:

12 41 7 834 214

Affected available inventory must not be sold.

Concerned are all parts delivered and shipped so far containing codes S35AN25 or S36AN25. Parts containing codes outside of those two provided are ok for use.

Your attention and information update is required on SRD Next>Parts Campaign by 05/07/2026.

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC857 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

TEC857 is valid from May 04, 2026, through May 18, 2026. The deadline for filing a claim under TEC857 is May 18, 2026. All parts must be returned to your facing RDC no later than June 01, 2026.

Please reorder the same part number as needed.

Affected Parts (NOT OK)	Non Affected Parts (OK)
All parts with the number S35AN25 or S36AN25 on the part label	All parts with a different number on the part label
more Information	