

**Condition**

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
RS e-tron GT	2022 – 2026	All	PR Code FT1
e-tron GT	2022 – 2025		
S e-tron GT	2026		
A6 allroad, RS 6 Avant, RS 7, A8, S8, Q7, SQ7, Q8, SQ8, and RS Q8	2023 – 2026		
A6, S6, A7, and S7	2023 – 2025		
e-tron, and e-tron Sportback	2023		
Q8 e-tron, Q8 Sportback e-tron, SQ8 e-tron, and SQ8 Sportback e-tron	2024		

REVISION HISTORY		
Revision	Date	Purpose
5	-	Revised header (Added MY 26) Revised <i>Condition</i> (Added model table)
4	04/15/2025	Revised header (Added MY 25) Revised <i>Warranty</i> (Updated labor operations)
3	02/15/2024	Revised <i>Warranty</i> (Updated labor operation)

**Customer states:**

Remote-controlled parking (remote park assist plus, or "RPA") is not working. The following message appears in the myAudi app when activating remote park assist plus:

**"Connection to vehicle required - please make sure you are near your vehicle to start the function".**

However, the customer is already near the vehicle.

**Workshop findings:**

- The customer complaint can be reproduced.

- No relevant DTCs are stored.

## NOTICE

The event memory entry “B187A00: Cancel parallel parking assist (symptom number 98341)” has no influence regarding this complaint.

## Technical Background

A Software related issue in roof antenna control unit -JX3- may cause the remote park assist plus not to function.

## Production Solution

Not Applicable.

## Service

Please perform a terminal 30 reset of the vehicle by disconnecting the 12 Volt battery -A-.

The procedure is described in the instructions in ElsaPro.

Please keep the 12V battery disconnected for approximately 20 minutes.

## Warranty

<b>Claim Type:</b>	<ul style="list-style-type: none"> <li>• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.</li> </ul>		
<b>Service Number:</b>	9113		
<b>Damage Code:</b>	0040		
<b>Labor Operations:</b>	GFF	0150 0010	See SRT with associated operations
	GFF	0150 0060	Time stated on the diagnostic protocol
	Loosen and secure battery ground strap	9785 0999	10 TU
<b>Claim Comment:</b>	As per TSB 2071986/5		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Please note the information on predecessors and items that are included and excluded in the repair operations as well as any associated tasks.

## Additional Information

All part and service references provided in this TSB (**2071986**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or

otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.