

INCOMPATIBLE PANNIERS ON TIGER SPORT MODELS

Triumph has identified incompatibility on certain panniers between the pannier rotating bushing and a specific batch of lock barrels. This affects some panniers designed to fit both the Tiger Sport 660 and Tiger Sport 800.

Any pannier manufactured **prior** to May 20th, 2025 may not be compatible with locks from certain batch numbers. Dealers are requested to return any in stock pannier kits or panniers that predate the product improvement.

Impacted Parts

- The part numbers affected are: A9501200, T9501201 & T9501202
- Parts manufactured prior to May 20th, 2025

- **Please note that the date on the label is day-first date format is known as dd-mm-yy (day-month-year), commonly used in Europe, the UK, and most of the world due to where the panniers are produced.**

- The production date can be identified on the printed barcode sticker applied to the packaging
- Any stock showing a date later than May 5th, 2025 will not be affected by this return.



If you are holding any affected inventory before the specified date, please submit an MRN exception case through TOL to swap for an unaffected unit. A picture of the date code should be included in the return case. Any returns on Panniers outside of the affected date code range are subject to the normal accessory return requirements listed in your Dealer Guide.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.