

Hot Topic

IMPORTANT Artura Software Platform Update Platform Levels - **PF4.14, PF5.6, PF6.7, PF7.2, PF4.7 and PF5.2**

An issue has been identified following update on McLaren Artura vehicles to software platforms PF4.14, PF5.6, PF6.7, PF7.2, PF4.7 and PF5.2 whereby the transmission calibration sequence may fail to complete if required to be run. In the case this is experienced please submit a Technical Request.

Please note there is **NO requirement** to complete the transmission calibration sequence following platform update so no issues are anticipated through completing the normal update process.

McLaren are pleased to announce that the latest software platforms for Artura (P16) and 750S (P28) are now live within the MDS2 tool.

For release notes and instructions on how to complete the required platform updates, please refer to the relevant software Knowledge Articles.

- KA-01557 McLaren Artura (P16) - Current Software Platform
- KA-01191 720S (P14) and 750S (P28) Current Software Platforms

Please ensure if you have vehicles in your retailer that the software is updated before vehicles are released.

There are several enhancements provided within the software with the topics below;

Artura

- New low voltage top up strategy to reduce battery drains
- HYCU reset strategy
- Wrong Actuator Movement enhancements

750S

- Negative Torque strategy enhancements avoiding drop to neutral scenarios
- For NA markets - Instrument cluster advanced seatbelt reminder