



Service Bulletin

Bulletin No.: PIT6467B

Date: June, 2026

PRELIMINARY INFORMATION

Subject: SES MIL / Fuel Gauge Drops To Empty / Stalls Due To Running Out Of Fuel / DTCs P3261 P3262 P3263

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 3500 HD	2025 - 2026		All	All	6.6L (L8T)	All
GMC	Sierra 3500 HD	2025 - 2026		All	All	6.6L (L8T)	All

Involved Region or Country	North America
Condition	Some customers may comment on any of the following: - SES MIL without any drivability issues with DTCs P3261, P3262, P3263 - Truck runs out of fuel with the fuel gauge indicating there is still fuel in the tank - Fuel gauge defaulting to empty, but there is still fuel in the rear tank
Cause	The cause of this condition could be the rear tank is not transferring fuel to the front tank.

Correction

The correction for this condition is Safety Recall N262544420-01: Safety Recall- Disabled Secondary Fuel Tank May Cause Vehicle Stall. Investigate Vehicle History (IVH) in the GM Global Warranty Management system MUST always be checked to confirm vehicle involvement and MUST be in OPEN status prior to beginning any required inspections and/or repairs. If your vehicle does not apply or the recall has been previously completed, then perform normal SI diagnostics.

Version	3
Modified	12/16/2025 - Created. 02/02/2026 - Updated Correction. 06/03/2026 Updated to add correction per N262544420-01.

