

 [26-BD-007H - Wiper Park Position Misalignment \(War Ext Z08\) \(posted 07.06.26\).pdf](#)

 [Warranty Extension Z08 - Wiper Park Position Misalignment - Dealer Notification \(posted 07.06.26\).pdf](#)

Hyundai Motor America (HMA) has launched Warranty Extension Z08: Wiper Park Position Misalignment: Wiper Motor Crank Arm Nut Replacement.

A. Affected Vehicles:

1. VIN Identification: Use the 'Vehicle Information' screen in WebDCS and look under the 'Factory Extended Warranty' section to determine vehicle applicability.

- a. 2025MY Tucson (NX4M) produced 06/05/2024 – 03/31/2025
 - i. Built by Kia Motors Mexico (KMX) – VIN starts with "3KM"
- b. 2022-25MY Tucson (NX4A) produced 05/26/2021 – 04/06/2025
 - i. Built by Hyundai Motors Manufacturing Alabama ("HMMA") – VIN starts with "5NM"
- c. 2022-25MY Santa Cruz (NXT) produced 02/03/2021 – 05/11/2025
 - i. Built by HMMA – VIN starts with "5NT"

B. Warranty Extension Description:

Some Tucson (NX4A and NX4M) and Santa Cruz (NXT) vehicles may have front wipers that do not return to the designated park position due to a loose wiper motor crank arm nut.

Hyundai is extending the warranty coverage for the wiper motor crank arm nut under this condition to 10 years / 100,000 miles from the date of original retail delivery or date of first use (whichever comes first) and is valid for original and subsequent owners.

Follow the procedure in **Technical Service Bulletin (TSB) 26-BD-007H** to replace the wiper motor crank arm nut to address this condition.

Please note that any vehicles within 10 years / 100,000 miles are covered by this TSB, even if the vehicle is still within the New Vehicle Limited Warranty (NVLW) of 5 years / 60,000 miles.

C. Parts Ordering/Information:

1. An applicable Z08 VIN will be required to order the crank arm nut.
2. Parts may be ordered through the normal WebDCS Process.
3. Please see TSB for the latest parts information.

D. Warranty Extension Documents:

1. TSB 26-BD-007H

- a. Available on [Hyundaidealer.com](#) > Service > Service Programs > HMA Tech Info > Campaign

2. Dealer Notification

- a. Available on [Hyundaidealer.com](#) > Service > Service Programs > HMA Tech Info > Service News

E. Action Required (ONLY if customer presents front wipers position concern as noted above):

1. Confirm VIN eligibility for warranty extension Z08 via WebDCS and that vehicle is within 10 years/100,000 miles.
2. **Follow TSB 26-BD-007H** to perform the service procedure only after confirming customer's front wipers position concern.
3. **Submit campaign claim** once the service procedure is completed.

We appreciate your continued partnership and commitment to our Hyundai customers.

Thank you for your patience and understanding.

Warranty Campaign Team

Hyundai Motor America