

2022 MY F-150

Powertrain Control Module - PCM

PT-26.11.3

Safety Recall 25S75

Powertrain Control Module

As a reminder, ensure you have a recurring Software Update schedule set in order to receive important updates for your vehicle. Visit the Software Update settings in-vehicle or on your mobile app.

1

PT-26.11.3

"We have updated the software in your Powertrain Control Module (PCM). On your vehicle, it is possible to have a loss of fuel pressure and flow from the fuel tank due to fuel pump failure. This can cause a lack of fuel delivery to the engine and result in an engine stall while driving. Fuel pump failure is more likely to occur under low fuel or warm weather and hot fuel conditions in the fuel tank. This completes Safety Recall 25S75.

If you experience poor engine performance (misfiring or running rough), a check engine light, or a reduction in engine power, please contact your dealership for assistance."