

SS 584261 FCCC MT45G & MT55G Power Steering Oil Cooler Replacement Parts (306)

Applicable Vehicles

2010 2025 FCCC MT45G & MT55G

Symptoms

Original power steering oil cooler 05-29962-000 is NLA (no longer available).

Issue

Original P/S oil cooler 05 29962 000 is NLA and being replaced with 05 38367 000, but additional parts are required, as 05 29962 000 & 05 38367 000 are **NOT** interchangeable.

Solution

FCCC Engineering developed replacement "kit" of parts as seen on the attached Work Instructions.

This "kit" of parts will **NOT** be sold through Paragon, but the replacement parts are:

05-38367-000-oil cooler (1)

N913023 008003-nut (2)

23-11357-008-clamp (4)

23-12240-019-spacer (2)

Please see the attached Work Instructions.

Normal warranty would apply IF applicable.

Labels :

Step Vans

Add tags

Attachments



A thumbs-up icon representing a kudos or like action.

0 Kudos

Comment



KIT-P/S COOLER, MT45G/MT55G

REF	Part Number	Description	Qty
1	05-38367-000	COOLER-FLUID,POWER STEERING,MT	1
2	913023 008003	NUT-HEX FLG,M8X1.25,PRVL TRQ	2
3	23-11357-008	CLAMP-HOSE,SGL,CUSH, .500 DIA	4
4	23-12240-019	SPACER-AL,.375 ID.75 OD X .19	2


1. THIS KIT IS FOR – MT45G/MT55G EQUIPPED WITH 05-29962-000
POWER STEERING COOLER. REFERENCE MODULE 533.

2. ITEM 4 NOT REQUIRED WHEN CONDENSER IS NOT EQUIPPED,
REFERENCE MODULE 698.

3. FASTENER TORQUE CALLED OUT IN BILL OF MATERIAL.



With condenser, module 698



Without condenser, module 698