



To: All Subaru Retailers
From: Subaru of America, Inc. – Service Quality
Date: July 28, 2026
Re: **WRH-26 Certification Label Non-Compliance Recall- Parts and SSLP Process Updates**

We are happy to provide an update regarding 2025-2026 Forester, 2026 Crosstrek, and 2019-2026 Ascent vehicles in retailer inventory affected by the WRH-26 Certification Label Non-Compliance Recall.

- The WRH-26 recall status for the affected vehicles in retailer inventory included in the stop sale and all affected SSLP inventory have been updated to an “Open-Limited Parts Available” status. Corrective labels have been sent only for vehicles in an Open-Limited parts available status. All remaining affected vehicles are in an “Open-Remedy not yet available status”. **Coverage must be confirmed by using the Vehicle Coverage Inquiry function on subarunet.com prior to repair.**
- We will be shipping the labels below directly to all Subaru retailers today and they will begin arriving to retailers on Wednesday 7/29. You can view these orders in RPM and they will reference the WRH-26 recall.

Models	Part Number	ID Letter	Expected usage
2026 Crosstrek	99095FN000	F	With inventory arriving 7/29, retailers have been sent labels to handle all stop sale and SSLP inventory.
2019-2026 Ascent	99095XC000	H	With inventory arriving 7/29, retailers have been sent labels to handle all stop sale and SSLP inventory.
2025 Forester (Gas)	99095SL000	M	Retailer sent labels to handle affected stop sale and SSLP vehicles (arriving 7/29).
2025 Forester (hybrid, 18 inch)	99095SL030	C	Retailer sent labels to handle affected stop sale and SSLP vehicles (arriving 7/29).
2025 Forester (hybrid, 19 inch)	99095SL040	D	Retailer sent labels to handle affected stop sale and SSLP vehicles (arriving 7/29).
2026 Forester (Gas)	99095SL020	K	Retailer sent labels to handle affected stop sale and SSLP vehicles (arriving 7/29).

NOTE: *We are very limited in the inventory that is being received and will be auto shipping parts as inventory arrives. Please do not submit orders for these part numbers. Any order placed will be cancelled. Similarly, please do not contact the PICs to request additional inventory.*

- With the shipment of the parts above, retailers will have corrective labels to handle all WRH-26 affected stop sale and SSLP vehicles. **As a result, effective immediately, the interim SSLP process can no longer be used. The label modification was intended as an interim process to allow affected SSLP vehicles to be utilized. Label Modification does not complete the WRH-26**

recall, only installation of the corrective labels remedies the WRH-26 recall. With corrective labels being sent to retailers to handle all affected SSLP vehicles, and SSLP vehicle that have not received corrective labels will be being applied back to the WRH-26 recall, resulting in a SSLP utilization hold. The only way to allow these SSLP vehicles to be utilized is to install the corrective labels and submit a WRH-26 recall claim. Once approved, these SSLP vehicles will be able to be utilized.