

GPOP - Issue Review System

Part Number: 68470078A\$

Part Description: PUMP, Auxiliary Coolant

Issue Description: Before replacing the Auxiliary Coolant Pump, please perform the following steps:
1) Key ON/OFF and let the after-run pump run for at least 20 minutes before moving on to step #2. 2) Inspect the pump connector area for presence of water. 3) Inspect the pump connector for corrosion. 4) Inspect the pump for coolant contamination as this can cause the pump to stall. 5) Inspect battery terminals for damage to rule out a battery drainage issue. 6) Ensure the PCM is up-to-date with the latest available flash. If correct repair is not performed then the claim or condition will be recovered by Warranty Operations.