



Mitsubishi Motors North America, Inc.
PARTS BULLETIN

SUBJECT:

Outlander / Outlander PHEV
Front Bumper Mislabeled Issue

No: PB-DG-001-26

Date: 7-28-2026

Model: Model Years 2025-26
Outlander / Outlander PHEV

PURPOSE:

The purpose of this parts bulletin is to correct a mislabeling issue caused by a mid-cycle design change. Dealers need to manually separate and relabel parts based on physical differences to ensure proper application.

BACKGROUND:

The FACE, FR BUMPER for the Outlander & Outlander PHEV received modifications in December of 2024 as a running change. There are four (4) different variations based upon bumper hole pattern for headlamp washer, parking sensors, etc. The revision added mounting holes for the FCM module, which was relocated inside the bumper beginning with the 2026 model year. Old and new designs were not given separate part numbers, leading to mixed inventory with identical part number labels. This is causing issues due to old style parts unable to be used on 26MY units, but the new style can be used on 26MY and prior.

ACTION:

- Inspect inventory and separate parts by design (refer to pictures below).
- If parts are the old design, no action needed.
- If parts are the new design, re-label box to correct part numbers (Refer to Table A).
- Adjust inventory records accordingly to ensure the correct part number and quantity is shown in dealer management system.

Old Design: No mounting holes on inside of vertical reinforcements



New Design: Equipped with mounting holes on inside of vertical reinforcements (shown circled in red)



TABLE A


PART NAME	VARIATION	OLD PART # (No mounting holes for FCM Module)	NEW PART # (With 4 mounting holes for FCM Module)	MODEL
FACE, FR BUMPER	No Holes	62012W900P	62012WD50P	Outlander
FACE, FR BUMPER	Holes for Head Lamp Washer	62012W910P	62012WD60P	Outlander & Outlander PHEV
FACE, FR BUMPER	Holes for Front Parking Sensors	62012W920P	62012WD70P	Outlander
FACE, FR BUMPER	Holes for Head Lamp Washer & Parking Sensors	62012W930P	62012WD80P	Outlander & Outlander PHEV



Parking Assist Holes



Headlamp Washer Holes

**ADDITIONAL INFORMATION:**

Contact your designated DAM or Facing PDC for questions.