



Service Bulletin

Bulletin No.: PIT6539

Date: August, 2026

PRELIMINARY INFORMATION

Subject: Heated Seats Inoperative When Interior Temp Is Above 86 Degrees F

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade	2026		All	All	All	All
Cadillac	Escalade ESV	2026		All	All	All	All
Chevrolet	Suburban	2026		All	All	All	All
Chevrolet	Tahoe	2026		All	All	All	All
GMC	Yukon	2026		All	All	All	All
GMC	Yukon XL	2026		All	All	All	All

Involved Region or Country	North America
Condition	A customer may comment that the heated seats are inoperative when interior temperature is above 86°F. The heated seats may have worked when vehicle was first driven in the morning but then stopped working after a shutting vehicle off for a period of time. This is due to the interior temp of the vehicle rising above 86°F as the ambient temp rose during the day.
Cause	The cause of the condition may be a software anomaly in the Body Control Module (BCM.)

Correction

Engineering is currently investigating. In the meantime, please advise the customer to drive the vehicle. The PI will be updated or replaced with TSB once a determination has been made.

Version	1
Modified	08/26/2026 - Created

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2026 General Motors. All Rights Reserved.