



Connection offline

Technical Service Bulletin

Transaction No.: **2063528/5**

48 Service Info : Engine noises in vehicle interior

Release date: Aug 21, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
Q7	2017 – 2026	All	Not applicable
A4, and A4 allroad	2017 – 2025		
S4, A5 Sportback, S5 Sportback, Q5, and SQ5	2018 – 2025		
A5, A5 Cabriolet, S5, and S5 Cabriolet	2018 – 2024		
RS 5	2018 – 2019 2021 – 2024		
Q8	2019 – 2026		
RS 5 Sportback	2019 2021 – 2025		
SQ7, SQ8, and RS Q8	2019 – 2026		
Q5 Sportback, and SQ5 Sportback	2021 – 2025		

REVISION HISTORY		
Revision	Date	Purpose
5	-	Revised header (Added Model/Model Year)
4	06/29/2023	Revised header (Added Model Year) Revised <i>Warranty</i> (Informational only TSB)
3	04/28/2022	Revised header (Added Model Year)

Customer states:

- Noises can be heard from the engine compartment/front end when accelerating between 1500 and 2300 rpm. The noises are described as combustion noises, or as clattering or ticking from the injectors. The service info is intended to help identify possible sources of the noise.

Technical Background

Various (depending on source of noise).

The cause of the noise is not necessarily a fault in the injectors or other engine components.

Production Solution

Not applicable.

Service

A possible cause of noise being transmitted from the engine compartment is insufficient noise insulation at the opening for the intermediate steering shaft in the bulkhead.

1. Therefore, check whether the sealing boot is seated correctly on the intermediate steering shaft and on the bulkhead without any visible gaps (Figure 1).



Figure 1. Poor sealing on the intermediate shaft.

2. The noise may also be influenced by the height adjustment of the steering wheel.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2063528**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.