

WTL3 - Replacing Seal for Roof Module (Workshop Campaign)

Model Line: **Cayenne Electric (X1A)**

Model Year: **2026**

Concerns: **Roof assembly gasket**


Information: **On the affected vehicles, there is a possibility that the front left and right roof module seal was not applied correctly.**

As a result, the seal is not durable and can partially detach. Over the service life of the vehicle, this may lead to leaks in the area of the roof module.

Action: Replace seal on roof module.

Affected Vehicles: Only vehicles assigned to the campaign (see also PCSS Vehicle Information).

Installation Position:



Roof assembly gasket

Required tools

- Tools:
- Torque wrench 2-10 Nm (1.5-7.5 tlb.), e.g.: > V.A.G 1783 – Torque wrench 2-10 Nm (1.5-7.5 flb.)
 - > VAS 1978/14A – Hot air gun
 - > 9886/1 – Pressure roller

Required parts and materials

Parts Info:

Designation	Part no.	Quantity
> 1 piece seal for sunroof PAB877459B	PAB877459B	1 piece
> 1 set of fastening screws PAB898955	PAB898955	1 piece

Technical Information

Service

WTL3

ENU

WTL3

6

Material: **Required material** (usually already available in the Porsche Center)

Designation	Part no.	Quantity
Cleaning materials	WTL30000001*	1 piece

* For warranty processing, the **part number WTL30000001** with the designation 'Cleaning material' can be invoiced as an **additional part** in the warranty claim. Maximum amount \$2.70.

Replace seal on roof module

Work Procedure: Replace roof module seal.

For instructions, see: **60545500 Replacing front roof assembly seal**

Warranty processing



Information

The specified labor time was determined specifically for carrying out this campaign and includes all necessary preliminary and subsequent work. The labor time may differ from the labor time published in the Labor Operation List in the PCSS.

Scope 1: **Replace seal on roof module**

Labor time:

Replace seal on roof module

Remove and install front sliding-roof panel
Remove and install rear sliding-roof panel

Required parts:

PAB877459B	Seal for sliding roof	1 piece
PAB898955	Set of fastening screws	1 piece

Required material:

WTL30000001*	Cleaning materials	1 piece
--------------	--------------------	---------

* For warranty processing, the **part number WTL30000001** with the designation Cleaning material can be invoiced as an **additional part** in the warranty claim. Maximum amount \$2.70.

Damage number WTL3 066 000 2

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2026 Porsche Cars North America, Inc.