VQ-10322006-2200

Short Doubles 19

TRAFFIC CRASH REPORT

OH-1 (Rev. 10/99)

OHIO PUBLIC SAFETY — EDUCATION • SERVICE • PROTECTION

LOCAL REPORT #	CRASH SEVERITY	PRIVATE PROPERTY	HIT/SKIP	PHOTOS TAKEN	OH-2	OH-3	OH-1P	OTHER
10-0693-90	3 (1 FATAL, 3 PDO, 2 INJURY, 4 UNKNOWN)	'X' IF YES	1 (1 HIT/SKIP, 2 SOLVED, 3 UNSOLVED)	'X' IF YES: X	X	X		

N.C.I.C. #	REPORTING AGENCY	# UNITS	UNIT ERROR	DATE OF CRASH
OHP90	Ohio State Highway Patrol	01	01 (98 = ANIMAL, 99 = UNKNOWN)	07/21/2009

TIME OF CRASH	DAY OF WEEK	CITY	VILLAGE	TWP	NAME (OF CITY, VILLAGE OR TOWNSHIP)	COUNTY #	LATITUDE	LONGITUDE
1418	TUE			X	Oxford	22	41:20:51.29	82:48:24.48

CRASH OCCURRED ON

PREFIX	CRASH LOCATION	TYPE LOC	TYPE LOCATION POINT USED (1 NAMED STREET, 2 NUMBERED STREET, 3 NUMBERED ROUTE)	LOCATION INFORMATION
	IR0080	3		WB

AT REFERENCE

DIST REFERENCE	DIR	PREFIX	REFERENCE	REF POINT	REFERENCE POINT USED
.3M	E		109	06	01 STATE LINE; 02 INTERSECTION 2 STREETS; 03 COUNTY LINE; 04 HOUSE NUMBER; 05 TOWNSHIP BOUNDARY; 06 MILE POST; 07 CORPORATION LIMIT; 08 PLACE NAME W/O REFERENCE; 09 DRIVEWAY; 10 STREET OR ROUTE W/O REFERENCE

Motorist/Non-Motorist

A

UNIT #	# OF OCC.	NAME (LAST, FIRST, MIDDLE)
01	01	[redacted]

ADDRESS (STREET, CITY, STATE, ZIP CODE): [redacted], Pemberville, Ohio [redacted]

SOCIAL SECURITY NUMBER	DATE OF BIRTH	AGE	SEX	HOME PHONE #	WORK PHONE #
	08201951	57	M	[redacted]	[redacted]

DL STATE	DL #	LP STATE	LP #	INJURED TAKEN BY (1 NONE, 2 EMS, 3 POLICE, 4 OTHER, 5 UNKNOWN)	TRANSPORTED BY	INJURED TAKEN TO
OH	[redacted]	IN	[redacted]			

OWNER NAME (IF SAME, WRITE "SAME")	ADDRESS (STREET, CITY, STATE, ZIP CODE)
Services, United Parcel	3147 W 169th PL, Hammond, Indiana 46323

YEAR	MAKE	MODEL	COLOR	INSURANCE COMPANY	TOWING SERVICE	OWNER PHONE #
2007	MACK	Conventional	GRY/BRO	Liberty Mutual	Charlies	(419)891-6700

OFFENSE CHARGED	OFFENSE DESCRIPTION	CITATION #	LOCAL CODE 'X' IF YES

B

UNIT #	# OF OCC.	NAME (LAST, FIRST, MIDDLE)

ADDRESS (STREET, CITY, STATE, ZIP CODE):

SOCIAL SECURITY NUMBER	DATE OF BIRTH	AGE	SEX	HOME PHONE #	WORK PHONE #

DL STATE	DL #	LP STATE	LP #	INJURED TAKEN BY (1 NONE, 2 EMS, 3 POLICE, 4 OTHER, 5 UNKNOWN)	TRANSPORTED BY	INJURED TAKEN TO

OWNER NAME (IF SAME, WRITE "SAME")	ADDRESS (STREET, CITY, STATE, ZIP CODE)

YEAR	MAKE	MODEL	COLOR	INSURANCE COMPANY	TOWING SERVICE	OWNER PHONE #

OFFENSE CHARGED	OFFENSE DESCRIPTION	CITATION #	LOCAL CODE 'X' IF YES

Occupant

C

UNIT #	NAME (LAST, FIRST, MIDDLE)	HOME PHONE #	DATE OF BIRTH	AGE	SEX

ADDRESS (STREET, CITY, STATE, ZIP CODE):

INJURED TAKEN BY (1 NONE, 2 EMS, 3 POLICE, 4 OTHER, 5 UNKNOWN)	TRANSPORTED BY	INJURED TAKEN TO

D

UNIT #	NAME (LAST, FIRST, MIDDLE)	HOME PHONE #	DATE OF BIRTH	AGE	SEX

ADDRESS (STREET, CITY, STATE, ZIP CODE):

INJURED TAKEN BY (1 NONE, 2 EMS, 3 POLICE, 4 OTHER, 5 UNKNOWN)	TRANSPORTED BY	INJURED TAKEN TO

SEATING POSITION	SAFETY EQUIPMENT	AIR BAG	AIR BAG SWITCH	EJECTION	TRAPPED	INJURIES
A: 01	A: 04	A: 5	A: 1	A: 1	A: 1	A: 1
B:	B:	B:	B:	B:	B:	B:
C:	C:	C:	C:	C:	C:	C:
D:	D:	D:	D:	D:	D:	D:

SEATING POSITION: 01 FRONT - LEFT (MC DRIVER); 02 FRONT - MIDDLE; 03 FRONT - RIGHT; 04 SECOND - LEFT (MC PASS); 05 SECOND - MIDDLE; 06 SECOND - RIGHT; 07 THIRD - LEFT (MC PASSENGER/SIDECAR); 08 THIRD - MIDDLE; 09 THIRD - RIGHT; 10 SLEEPER SECTION OF CAB; 11 ENCLOSED CARGO AREA; 12 UNENCLOSED CARGO AREA; 13 TRAILING UNIT; 14 EXTERIOR; 15 OTHER; 16 NON-MOTORIST; 17 UNKNOWN; BLANK FOR WITNESS

SAFETY EQUIPMENT — MOTORIST: 01 NONE USED; 02 SHOULDER BELT ONLY; 03 LAP BELT ONLY; 04 SHOULDER/LAP BELT; 05 CHILD SAFETY SEAT; 06 MC HELMET USED; 07 USE UNKNOWN — NON-MOTORIST: 08 NONE USED; 09 HELMET USED; 10 PROTECTIVE PADS; 11 REFLECTIVE CLOTHING; 12 LIGHTING; 13 OTHER; 14 UNKNOWN

AIR BAG: 1 NOT DEPLOYED; 2 DEPLOYED-FRONT; 3 DEPLOYED-SIDE; 4 DEPLOYED BOTH FRONT/SIDE; 5 NOT APPLICABLE; 6 UNKNOWN

AIR BAG SWITCH: 1 NOT PRESENT; 2 IN ON POSITION; 3 IN OFF POSITION; 4 UNKNOWN

EJECTION: 1 NOT EJECTED; 2 TOTALLY EJECTED; 3 PARTIALLY EJECTED; 4 NOT APPLICABLE; 9 UNKNOWN

TRAPPED: 1 NOT TRAPPED; 2 EXTRACTED BY MECHANICAL MEANS; 3 FREED BY NON-MECHANICAL MEANS; 4 UNKNOWN

INJURIES: 1 NO INJURY; 2 POSSIBLE; 3 NON-INCAPACITATING; 4 INCAPACITATING; 5 FATAL INJURY; 6 UNKNOWN

SUPPLEMENT * 'X' IF YES

HSY7001 — TOP COPY - ODPS — BOTTOM COPY - AGENCY

CAD Incident Number: LHP090721002305

19

UNIT NUMBERS
A: 0 1 | B:

NON-MOTORIST LOCATION
A: | B:

01 MARKED CROSSWALK AT INTERSECTION
02 INTERSECTION NO CROSSWALK
03 NON-INTERSECTION CROSSWALK
04 DRIVEWAY ACCESS CROSSWALK
05 IN ROADWAY
06 NOT IN ROADWAY
07 MEDIAN (BUT NOT SHOULDER)
09 ISLAND
09 SHOULDER
10 SIDEWALK
11 WITHIN 10 FEET OF ROADWAY (NOT SHOULDER, MEDIAN, SIDEWALK, ISLAND)
12 BEYOND 10 FEET OF ROADWAY (WITHIN TRAFFICWAY)
13 OUTSIDE TRAFFICWAY
14 SHARED PATHS OR TRAILS
15 UNKNOWN

TYPE OF UNIT
A: 1 4 | B:

MOTORIST
01 SUB-COMPACT
02 COMPACT
03 MID SIZE
04 FULL SIZE
05 MINIVAN
06 SPORT UTILITY VEHICLE
07 PICKUP
08 PANEL/VAN
09 SINGLE UNIT TRUCK; 2 AXLES, 6 TIRES
10 SINGLE UNIT TRUCK; 3+ AXLES
11 TRUCK/TRAILER
12 TRUCK TRACTOR (BOBTAIL)
13 TRACTOR/SEMI-TRAILER
14 TRACTOR/DOUBLE SHORT
15 TRACTOR/DOUBLE LONG
16 FIFTH WHEEL OR CONVERTER DOLLY
17 TRACTOR/TRIPLES
18 MOTORCYCLE
19 MOTORIZED BICYCLE
20 SCHOOL BUS
21 CHURCH BUS
22 PUBLIC BUS
23 OTHER BUS
24 POLICE VEHICLE
25 FIRE TRUCK
26 AMBULANCE/RESCUE
27 TAXI
28 MOTOR HOME
29 TRAIN
30 FARM VEHICLE
31 FARM EQUIPMENT
32 SNOWMOBILE
33 CONSTRUCTION EQUIPMENT
34 ALL OTHERS
NON-MOTORIST
35 ANIMAL W/RIDER
36 ANIMAL W/BUGGY
37 BICYCLE
38 PEDESTRIAN
39 PEDALCYCLIST
40 SKATER
41 OTHER-NON MOTORIST
42 UNKNOWN

IN EMERGENCY RESPONSE
A: | B:

1 NO
2 YES
3 UNKNOWN

DAMAGE SCALE
4

1 NONE
2 NON-FUNCTIONAL DAMAGE
3 FUNCTIONAL DAMAGE
4 DISABLING DAMAGE
5 SEVERE
6 UNKNOWN

DAMAGE AREA



MOST DAMAGED AREA
0 5

01 NONE
02 CENTER FRONT
03 RIGHT FRONT
04 RIGHT SIDE
05 RIGHT REAR
06 REAR CENTER
07 LEFT REAR
08 LEFT SIDE
09 LEFT FRONT
10 TOP AND WINDOWS
11 UNDERCARRIAGE
12 LOAD/TRAILER
13 TOTAL (ALL AREAS)
14 OTHER
15 UNKNOWN

POINT OF IMPACT
0 5

01 NONE
02 CENTER FRONT
03 RIGHT FRONT
04 RIGHT SIDE
05 RIGHT REAR
06 REAR CENTER
07 LEFT REAR
08 LEFT SIDE
09 LEFT FRONT
10 TOP AND WINDOWS
11 UNDERCARRIAGE
12 LOAD/TRAILER
13 TOTAL (ALL AREAS)
14 OTHER
15 UNKNOWN

ACTION
3

1 NON-CONTACT
2 NON-COLLISION
3 STRIKING
4 STRUCK
5 BOTH STRIKING AND STRUCK
9 UNKNOWN

STRIKING VEHICLE: OVERRIDE/UNDERRIDE
1

1 NO UNDERRIDE OR OVERRIDE
2 UNDERRIDE, COMPARTMENT INTRUSION
3 UNDERRIDE, NO COMPARTMENT INTRUSION
4 UNDERRIDE, COMPARTMENT INTRUSION UNKNOWN
5 OVERRIDE, MOTOR VEHICLE IN TRANSPORT
6 OVERRIDE OTHER VEHICLE
7 UNKNOWN

PRE-CRASH ACTIONS
0 1 | B:

MOTORIST
01 MOVEMENTS ESSENTIALLY STRAIGHT AHEAD
02 BACKING
03 CHANGING LANES
04 OVERTAKING/PASSING
05 TURNING RIGHT
06 TURNING LEFT
07 MAKING U-TURN
08 ENTERING TRAFFIC LANE
09 LEAVING TRAFFIC LANE
10 PARKED
11 SLOWING/STOPPED IN TRAFFIC
12 DRIVERLESS
13 OTHER
14 UNKNOWN
NON-MOTORIST
15 ENTERING/CROSSING IN SPECIFIED LOCATION
16 WALKING, RUNNING, JOGGING PLAYING, CYCLING
17 WORKING
18 PUSHING VEHICLE
19 APPROACHING/LEAVING VEHICLE
20 PLAYING/WORKING ON VEHICLE
21 STANDING
22 OTHER
23 UNKNOWN

CONTRIBUTING CIRCUMSTANCES
1 9 | B:

MOTORIST
01 NONE
02 FAILURE TO YIELD
03 RAN RED LIGHT, OR STOP SIGN
04 EXCEEDED SPEED LIMIT
05 UNSAFE SPEED
06 IMPROPER TURN
07 LEFT OF CENTER
08 FOLLOWED TOO CLOSELY/ACDA
09 IMPROPER LANE CHANGE/ DROVE OFF ROAD/ IMPROPER PASSING
10 IMPROPER BACKING
11 IMPROPER START FROM PARKED POSITION
12 STOPPED OR PARKED ILLEGALLY
13 OPERATING VEHICLE IN ERRATIC, RECKLESS, CARELESS, NEGLIGENT OR AGGRESSIVE MANNER
14 SWERVING TO AVOID (DUE TO WIND, SLIPPERY SURFACE, VEHICLE, OBJECT NON-MOTORIST IN ROADWAY, ETC)
15 FAILURE TO CONTROL
16 VISION OBSTRUCTION
17 DRIVER INATTENTION
18 FATIGUED/ASLEEP
19 OPERATING DEFECTIVE EQUIPMENT
20 LOAD SHIFTING/FALLING/SPILLING
21 OTHER IMPROPER ACTION
22 UNKNOWN
NON-MOTORIST
23 NONE
24 IMPROPER CROSSING
25 DARTING
26 LYING AND/OR ILLEGALLY IN ROADWAY
27 FAILURE TO YIELD RIGHT OF WAY
28 NOT VISIBLE (DARK CLOTHING)
29 INATTENTIVE
30 FAILURE TO OBEY TRAFFIC SIGN, SIGNALS, OR OFFICER
31 WRONG SIDE OF ROAD
32 OTHER
33 UNKNOWN

VEHICLE DEFECT CODE ONLY IF '19' SELECTED ABOVE
0 8 | B:

01 TURN SIGNALS
02 HEAD LAMPS
03 TAIL LAMPS
04 BRAKES
05 STEERING
06 TIRE BLOWOUT
07 WORN OR SLICK TIRES
08 TRAILER EQUIPMENT DEFECTIVE
09 MOTOR TROUBLE
10 DISABLED FROM PRIOR CRASH
11 OTHER DEFECTS

SEQUENCE OF EVENTS

A	B
0 8 (1)	(1)
3 0 (2)	(2)
(3)	(3)
(4)	(4)

NON-COLLISION
01 OVERTURN/ROLLOVER
02 FIRE/EXPLOSION
03 IMMERSION
04 JACKKNIFE
05 CARGO/EQUIPMENT LOSS/SHIFT
06 EQUIPMENT FAILURE
07 SEPARATION OF UNITS
08 RAN OFF ROAD RIGHT
09 RAN OFF ROAD LEFT
10 CROSS MEDIAN/CENTERLINE
11 DOWNHILL RUNAWAY
12 OTHER NON-COLLISION
13 UNKNOWN NONCOLLISION
COLLISION W/PERSON, VEHICLE, OR OBJECT NOT FIXED
14 PEDESTRIAN
15 PEDALCYCLE
16 RAILWAY VEHICLE
17 ANIMAL - FARM
18 ANIMAL - DEER
19 ANIMAL - OTHER
20 MOTOR VEHICLE IN TRANSPORT
21 PARKED MOTOR VEHICLE
22 WORK ZONE MAINTENANCE EQUIPMENT
23 OTHER MOVABLE OBJECT
24 UNKNOWN MOVABLE OBJECT
COLLISION WITH FIXED OBJECT
25 IMPACT ATTENUATOR/CRASH CUSHION
26 BRIDGE OVERHEAD STRUCTURE
27 BRIDGE PIER OR ABUTMENT
28 BRIDGE PARAPET
29 BRIDGE RAIL
30 GUARDRAIL FACE
31 GUARDRAIL END
32 MEDIAN BARRIER
33 HIGHWAY TRAFFIC SIGN POST
34 OVERHEAD SIGN POST
35 LIGHT/LUMINARIES SUPPORT
36 UTILITY POLE
37 OTHER POST, POLE OR SUPPORT
38 CULVERT
39 CURB
40 DITCH
41 EMBANKMENT
42 FENCE
43 MAILBOX
44 TREE
45 OTHER FIXED OBJECT
46 WORK ZONE MAINTENANCE EQUIPMENT
47 UNKNOWN FIXED OBJECT
48 OTHER
49 UNKNOWN

FIRST HARMFUL EVENT
A: 2 | B:

OF THE SEQUENCE OF EVENTS - WHICH ONE IS THE FIRST HARMFUL EVENT (1-4)

MOST HARMFUL EVENT
A: 2 | B:

OF THE SEQUENCE OF EVENTS - WHICH ONE IS THE MOST HARMFUL EVENT (1-4)

SPEED DETECTED
1

1 STATED
2 ESTIMATED SPEED

SPEED
6 5

POSTED SPEED
6 5

TRAFFIC CONTROL
1 2

01 NO CONTROLS
02 STOP SIGN
03 YIELD SIGN
04 TRAFFIC SIGNAL
05 TRAFFIC FLASHERS
06 SCHOOL ZONE
07 RAILROAD CROSSBUCKS
08 RAILROAD FLASHERS
09 RAILROAD GATES
10 CONSTRUCTION BARRICADE
11 POLICE OFFICER
12 PAVEMENT MARKINGS
13 CROSSWALK LINES
14 WALK/DON'T WALK SIGNAL
15 TRAFFIC CONTROL DEVICE INOPERATIVE MISSING, OBSCURED
16 OTHER

DIRECTION

FROM	TO	FROM	TO
3	4		

1 NORTH
2 SOUTH
3 EAST
4 WEST
5 NORTHEAST
6 NORTHWEST
7 SOUTHEAST
8 SOUTHWEST
9 UNKNOWN

CONDITION
1

1 APPARENTLY NORMAL
2 PHYSICAL IMPAIRMENT
3 EMOTIONAL
4 ILLNESS
5 FELL ASLEEP, FAINTED, FATIGUE, ETC
6 UNDER THE INFLUENCE OF MEDICATIONS/DRUGS/ALCOHOL
7 OTHER
8 UNKNOWN

ALCOHOL/DRUG SUSPECTED
1

1 NONE
2 YES - ALCOHOL SUSPECTED
3 YES - ABD NOT IMPAIRED
4 YES - DRUGS SUSPECTED
5 YES - ALCOHOL/DRUGS SUSPECTED
9 UNKNOWN

ALCOHOL TEST STATUS
1

1 NONE
2 TEST REFUSED
3 TEST GIVEN, CONTAMINATED SAMPLE/UNUSABLE
4 TEST GIVEN, RESULTS KNOWN
5 TEST GIVEN, RESULTS UNKNOWN
6 UNKNOWN

ALCOHOL TEST TYPE
1

1 NONE
2 BLOOD
3 URINE
4 BREATH
5 OTHER

ALCOHOL TEST RESULT
A: . | B: .

DRUG TEST STATUS
1

1 NONE
2 TEST REFUSED
3 TEST GIVEN, CONTAMINATED SAMPLE/UNUSABLE
4 TEST GIVEN, RESULTS KNOWN
5 TEST GIVEN, RESULTS UNKNOWN
6 UNKNOWN

DRUG TEST TYPE
1

1 NONE
2 BLOOD
3 URINE
4 OTHER

DRUG TEST(S) RESULT

A		B	
1	2	1	2

1 NONE
2 MARIJUANA
3 COCAINE
4 OPIATES
5 AMPHETAMINES
6 PCP
7 OTHER
8 UNKNOWN AT TIME OF REPORTING

TYPE OF INTERSECTION
0 1

01 NOT AN INTERSECTION
02 FOUR-WAY INTERSECTION
03 T-INTERSECTION
04 Y-INTERSECTION
05 TRAFFIC CIRCLE/ROUNDABOUT
06 FIVE-POINT, OR MORE
07 ON RAMP
08 OFF RAMP
09 CROSSOVER
10 DRIVEWAY/ACCESS
11 RAILWAY GRADE CROSSING
12 SHARED-USE PATHS OR TRAILS
13 UNKNOWN

OCCURRENCE
1

1 ON ROADWAY
2 ON SHOULDER
3 IN MEDIAN
4 ON ROADSIDE
5 ON GORE
6 OUTSIDE TRAFFICWAY
7 UNKNOWN

ROAD CONTOUR
3

1 STRAIGHT LEVEL
2 STRAIGHT GRADE
3 CURVE LEVEL
4 CURVE GRADE

ROAD CONDITION

PRIMARY	SECONDARY
0 1	

01 DRY
02 WET
03 SNOW
04 ICE
05 SAND, MUD, DIRT, OIL, GRAVEL
06 WATER (STANDING, MOVING)
07 SLUSH
08 DEBRIS**
09 RUT, HOLES, BUMPS, UNEVEN PAVEMENT**
10 OTHER
11 UNKNOWN

**SECONDARY ROAD CONDITIONS ONLY

SUPPLEMENT * 'X' IF YES

LOCAL REPORT #*: 10-0693-90

TOP COPY - ODPS BOTTOM COPY - AGENCY

CAD Incident Number - LHP090721002305

Narrative

Unit #1 was westbound on I.R. 80 at mile post #109.3. #1's air line for the trailer brakes disconnected causing the trailer brakes for the short double trailers to engage. #1's trailer brakes engaged causing the trailers tires to skid. #1's driver turned to the right to get off th roadway causing the rear trailer to strike the guard rail.

MANNER OF COLLISION OR IMPACT: 1
1 NOT COLLISION BETWEEN TWO VEHICLES IN TRANSPORT
2 REAR-END
3 HEAD-ON
4 REAR-TO-REAR
5 BACKING
6 ANGLE
7 SIDESWIPE, SAME DIRECTION
8 SIDESWIPE, OPPOSITE DIRECTION
9 UNKNOWN

SCHOOL BUS RELATED: 1
1 NO
2 YES, DIRECTLY INVOLVED
3 YES, INDIRECTLY INVOLVED
4 UNKNOWN

WORK ZONE RELATED: 1
1 NO
2 YES
3 UNKNOWN

WEATHER: 01
01 CLEAR
02 CLOUDY
03 FOG, SMOG, SMOKE
04 RAIN
05 SLEET, HAIL (FREEZING RAIN DRIZZLE)
06 SNOW
07 SEVERE CROSSWINDS
08 BLOWING SAND, SOIL, DIRT, SNOW
09 OTHER
10 UNKNOWN

TYPE OF WORK ZONE:
1 LANE CLOSURE
2 LANE SHIFT/CROSSOVER
3 WORK ON SHOULDER OR MEDIAN
4 INTERMITTENT/MOVING WORK
5 OTHER

LIGHT CONDITIONS — PRIMARY: 1 — SECONDARY:
1 DAYLIGHT
2 DAWN
3 DUSK
4 DARK - LIGHTED ROADWAY
5 DARK - NOT LIGHTED
6 DARK - UNKNOWN LIGHTING
7 GLARE
8 OTHER
9 UNKNOWN

LOCATION OF CRASH IN WORK ZONE:
1 BEFORE FIRST WORK ZONE WARNING SIGN
2 ADVANCE WARNING AREA
3 TRANSITION AREA
4 ACTIVITY AREA

WORKERS PRESENT:
1 NO
2 YES
3 UNKNOWN

Diagram



Truck/Bus

UNIT #: 01

THE CRASH INVOLVED ONE OR MORE OF THE FOLLOWING:
A TRUCK (MOTOR VEHICLE) WITH A GVWR MORE THAN 10,000 POUNDS; OR
A TRUCK (MOTOR VEHICLE) WITH A HAZARDOUS MATERIALS PLACARD; OR
A BUS DESIGNED FOR AT LEAST 8 PERSONS, INCLUDING DRIVER.

AND

THE CRASH RESULTED IN ONE OR MORE OF THE FOLLOWING:
A FATALITY; OR
AN INJURY REQUIRING TRANSPORTATION FOR IMMEDIATE MEDICAL TREATMENT; OR
AT LEAST ONE VEHICLE WAS TOWED DUE TO DISABLING DAMAGE OR REQUIRED INTERVENING ASSISTANCE BEFORE PROCEEDING UNDER IT'S OWN POWER

COMPANY (FROM SHIPPING PAPERS): UNITE PARCEL SERVICES
COMPANY PHONE: (419)891-6700
ADDRESS (STREET, CITY, ST, ZIP CODE): 1550 HOLLAND RD, Maumee, Ohio 43537

US DOT	ICC MC	PUCO	TRAILER LP ST.	TRAILER LP YEAR	TRAILER LP #	PLACARD #	# DIA.
021600		[redacted]	IN	2009	[redacted]		

CARGO BODY TYPE: 03
01 NOT APPLICABLE
02 BUS (9-15 INCLUDING DRIVER)
03 VAN/ENCLOSED BOX
04 GRAIN/CHIPS/GRAVEL
05 POLE
06 CARGO TANK
07 FLATBED
08 DUMP
09 CONCRETE MIXER
10 AUTO TRANSPORTER
11 GARBAGE/REFUSE
12 OTHER
13 UNKNOWN

WEIGHT (GVWR): 2
1 LESS/EQUAL 10,000
2 10,001 - 26,000
3 MORE THAN 26,000

COL CLASS: 1
1 CLASS A
2 CLASS B
3 CLASS C
4 CLASS M
5 CLASS D

HAZARDOUS MATERIALS PLACARD: 1
1 NO
2 YES
3 UNKNOWN

HAZARDOUS MATERIALS RELEASED: 1
1 NO
2 YES
3 NOT APPLICABLE
4 UNKNOWN

Police Action

DATE CRASH REPORTED	TIME REC CALL	DISPATCH	ARRIVED	CLEARED	OTHER	TOTAL MINUTES
07/21/2009	1418	1418	1421	1630	120	0252

OFFICER'S NAME*: Bracy, Brian
BADGE #*: 0115
CHECKED BY: TECURRAN
DATE REPORT FILED*: 07/26/2009

REPORT TAKEN BY: 1 (1 POLICE AGENCY, 2 MOTORIST)
REPORT TAKEN AT: 1 (1 SCENE, 2 STATION, 3 OTHER)
SUPPLEMENT (*"X" IF YES):
LOCAL REPORT #*: 10-0693-90

TOP COPY - ODPS BOTTOM COPY - AGENCY

CAD Incident Number - LHP090721002305

OHIO TRAFFIC ACCIDENT - DIAGRAM/NARRATIVE CONTINUATION OH-2 (REV. 1/82)

LOCAL REPORT NUMBER	REPORTING AGENCY	DATE OF ACCIDENT
10-0693-90	Ohio State Highway Patrol	07/21/2009
IN COUNTY OF	ACCIDENT LOCATION	
Erie	IR0080	

DAMAGE ANALYSIS

UNIT #1
YEAR ---------- 2007
MAKE ---------- MACK
MODEL ---------- CONVENTIONAL
REG ---------- [redacted] IN
VIN # ---------- 1M1AK02Y17N[redacted]
COLOR ---------- BROWN/GRAY
INSURANCE ------- LIBERTY MUTUAL POLICY #[redacted]
DAMAGED AREA - NONE

UNIT# 1'S FRONT TRAILER
YEAR ---------- 1996
MAKE ---------- STOUGHTON
MODEL ---------- VAN/ENCLOSED BOX
REG ---------- [redacted] IL
VIN # ---------- 1DW1C2819TB[redacted]
COLOR ---------- SILVER
DAMAGE ---------- REAR RIGHT TIRE HAS RUB MARKS FROM GUARD RAIL
LOAD INFO --------- BULK FREIGHT NOT DAMAGED

UNIT # 1'S REAR TRAILER
YEAR ---------- 2007
MAKE ---------- STOUGHTON
MODEL ---------- VAN/ENCLOSED BOX
REG ---------- [redacted] IN
VIN # ---------- 1GRAA56137K[redacted]
COLOR ---------- SILVER
DAMAGE ---------- RIGHT REAR TIRES HAVE IMPACT MARKS ON RIMS AND TIRES
LOAD INFO --------- BULK FREIGHT NOT DAMAGED

NOTE - FIELD SKETCH IS OF THE SKID MARKS ON THE ROADWAY FROM UNIT # , THE DRIVER OF UNIT # 1 MOVED THE VEHICLE OUT OF ROADWAY AND AWAY FROM THE SCENE PRIOR TO MY ARRIVAL.

NOTE - THE DEFECTIVE TRAILER EQUIPMENT WAS A BRAKE AIR HOSE THAT DISCONNECTED WHILE THE VEHICLE WAS IN MOTION.

NOTE - 70 FEET OF GUARD RAIL WAS DAMAGED IN THE CRASH AND (12) STEEL I-BEAM POST.

NOTE - UNIT # 1 DID NOT NEED TO BE TOWED FROM THE SCENE BUT A SERVICE TRUCK DID CHANGE 2 FLAT TIRES ON THE REAR TRAILER.

	AE	FE	DESCRIPTIONS
A	75.10E	14.8S	START OF LF OUTER TIRE SKID MARKS
B	76.1E	15.8S	START OF LF INNER TIRE SKID MARKS
C	105.3E	20.9S	START OF RT INNER TIRE SKID MARKS
D	106.7E	21.9S	START OF RT OUTER TIRE SKID MARKS
E	402.1E	0	RT OUTER TIRE SKID MARKS OFF ROADWAY
F	405.7E	0	RT INNER TIRE SKID MARKS OFF ROADWAY
G	435.2E	0	LF INNER TIRE SKID MARKS OFF ROADWAY
H	442.4E	0	LF OUTER TIRE SKID MARKS OFF ROADWAY
I	458.10N	11.5N	IMPACT MARK FORM UNIT #1 STRIKING GUAR RAIL
J	625.2E	10.5N	END OF RT OUTER TIRE SKID

OFFICERS SIGNATURE	BADGE NO.
	0115

CAD Incident Number - LHP090721002305

OHIO TRAFFIC ACCIDENT - DIAGRAM/NARRATIVE CONTINUATION **OH-2 (REV. 1/82)**

LOCAL REPORT NUMBER	REPORTING AGENCY	DATE OF ACCIDENT
10-0693-90	Ohio State Highway Patrol	07/21/2009
IN COUNTY OF	ACCIDENT LOCATION	
Erie	IR0080	

MARKS

K	625.2E	9.6N	END OF RT INNER TIRE SKID MARKS
L	646.10E	7.2N	END OF LF INNER TIRE SKID MARKS
M	646.9E	5.11N	END OF LF OUTER TIRE SKID MARKS
N	647.11E	0	END OF LF INNER TIRE SKID MARKS
O	648.1E	0	END OF LF OUTER TIRE SKID MARKS
P	650.7E	8.7N	END OF RT OUTER TIRE SKID MARKS
Q	651.5E	7.3N	END OF RT INNER TIRE SKID MARKS

RP = MILE POST # 109.3 W.B.
RP - PNT "O" = 13.0
PNT "O" = WHITE NORTH FOG LINE OF I.R. 80 W.B.
ROAD CONDITIONS = DRY,ASPHALT,CLEAN ROAD SURFACE
WEATHER CONDITIONS = DRY,CLEAR, 77 DEGREES, NO ADVERSE CONDITIONS

OFFICERS SIGNATURE	BADGE NO.
	0115

HSY 7002

CAD Incident Number - LHP090721002305

VQ-10322006-2200

OHIO TRAFFIC ACCIDENT - DIAGRAM/NARRATIVE CONTINUATION **OH-2 (REV. 1/82)**

LOCAL REPORT NUMBER	REPORTING AGENCY	DATE OF ACCIDENT
10-0693-90	Ohio State Highway Patrol	07/21/2009
IN COUNTY OF	**ACCIDENT LOCATION**	
Erie	IR0080	



NOT TO SCALE

OFFICERS SIGNATURE	BADGE NO.
	0115

HSY 7002

CAD Incident Number - LHP090721002305

OHIO TRAFFIC CRASH WITNESS STATEMENT **OH-3 REV 1/82**

LOCAL REPORT NUMBER	REPORTING AGENCY	DATE OF CRASH
10-0693-90	Ohio State Highway Patrol	07/21/2009

FOR LOCAL USE ONLY - DO NOT SUBMIT TO THE STATE EXCEPT FOR FATAL CRASHES

I, [redacted] (PRINTED) HEREBY MAKE THIS VOLUNTARY STATEMENT TO

Bracy, Brian (OFFICERS NAME) AT IR0080 (LOCATION)

ADDRESS OF WITNESS [redacted] Pemberville, Ohio [redacted]	PHONE [redacted]
SIGNATURE OF WITNESS	OFFICERS SIGNATURE

HSY 7003 1/82

CAD Incident Number - LHP090721002305