INFORMATION Redacted PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

PE16-013

NISSAN

11-16-2016

ATTACHMENT B

Request TWO Supporting Documents

Field Reports

3N1CN7AP2CL[redacted]

LOW FREQUENCY DATA

VEHICLE SPEED

TIME	DATA
-7s	0mph
-6s	0mph
-5s	0mph
-4s	0mph
-3s	0mph
-2s	0mph
-1s	0mph
0s	0mph
1s	0mph
2s	0mph
3s	0mph
4s	0mph
5s	0mph
6s	D.N.A.

ENGINE REVOLUTION

TIME	DATA
-7s	718rpm
-6s	712rpm
-5s	715rpm
-4s	709rpm
-3s	709rpm
-2s	715rpm
-1s	712rpm
0s	709rpm
1s	712rpm
2s	715rpm
3s	709rpm
4s	709rpm
5s	715rpm
6s	325rpm

LOW FREQUENCY DATA

THROTTLE PEDAL POSITION

TIME	DATA
-7s	0%
-6s	0%
-5s	0%
-4s	0%
-3s	0%
-2s	0%
-1s	0%
0s	0%
1s	0%
2s	0%
3s	0%
4s	0%
5s	0%
6s	0%

STEERING ANGLE

TIME	DATA
-7s	64deg
-6s	64deg
-5s	64deg
-4s	64deg
-3s	64deg
-2s	68deg
-1s	68deg
0s	67deg
1s	67deg
2s	67deg
3s	67deg
4s	67deg
5s	67deg
6s	D.N.A.

LOW FREQUENCY DATA

BRAKE PEDAL SW STATE

TIME	DATA
-7s	Off
-6s	Off
-5s	Off
-4s	Off
-3s	Off
-2s	Off
-1s	Off
0s	Off
1s	Off
2s	Off
3s	Off
4s	Off
5s	Off
6s	Off

GEAR POSITION

TIME	DATA
-7s	P or N
-6s	P or N
-5s	P or N
-4s	P or N
-3s	P or N
-2s	P or N
-1s	P or N
0s	P or N
1s	P or N
2s	P or N
3s	P or N
4s	P or N
5s	P or N
6s	D.N.A.

LOW FREQUENCY DATA

BUCKLE SW STATE[DR]

TIME	DATA
-7s	Off
-6s	Off
-5s	Off
-4s	Off
-3s	Off
-2s	Off
-1s	Off

BUCKLE SW STATE[AS]

TIME	DATA
-7s	On
-6s	On
-5s	On
-4s	On
-3s	On
-2s	On
-1s	On

LOW FREQUENCY DATA

DIAGMUXON STATE

TIME	DATA
-7s	On
-6s	On
-5s	On
-4s	On
-3s	On
-2s	On
-1s	On
0s	On
1s	On
2s	On
3s	On
4s	On
5s	On
6s	Off

STATIC DATA

MAX.FRONTAL G&TIME

	FRONTAL	TIME
	3.6G	12ms

MAX.LATERAL G&TIME

	FRONTAL	TIME
	6.2G	15ms

STATIC DATA

A/B W/L STATE

	STATE	
	Off	

IGN CYCLE

		CYCLE
	Event	6039count
	Download	6072count

STATIC DATA

OPERATION TIME

		TIME
	Event	1849hour
	Download	1857hour

D/L COUNT AFTER EVENT

	STATE	
	1count	

STATIC DATA

EDR RECORDING COMPLETE

	STATE	
Priority 1	SUCCESS	
Priority 2	SUCCESS	
Priority 3	SUCCESS	
Priority 4	SUCCESS	

GAP TIME FOR EDR

		TIME
	High Freq	11count
	Low Freq	41count

STATIC DATA


CAN ABNORMALITY


	STATE	
	NORMAL	


SYSTEM	AIR BAG
PART NUMBER	f122
VIN	3N1CN7AP2CL[redacted]


f	00	r	01	a0	D200	a1	8600
a2	5600	a3	9600	a4	0000	a5	0000
a6	0000	a7	0000	a8	0000	a9	0000
aa	0000	ab	0000	ac	0000	ad	0000
ae	0000	af	0000	A1	0000	A2	0000
A3	0000	A4	0000	A5	0000	B1	0000
B2	0000	B3	0000	B4	0000	B5	0000
C1	0000	C2	0000	C3	0000	C4	0000
C5	0000	D1	0000	D2	0000	D3	0000
D4	0000	D5	0000	E1	0000	E2	0000
E3	0000	E4	0000	E5	0000	F1	00
F2	00	G	00	U	0C	I1	FF
J1	FF	K1	FF	L1	FF	M1	05
I2	FF	J2	FF	K2	FF	L2	FF
M2	00	IR	FF	JR	FF	KR	02
LR	FF	MR	FF	IL	05	JL	03
KL	02	LL	FF	ML	03	R	43
S1	55	S2	55	S3	55	S4	8C
S5	8D	S6	8D	S7	8D	S8	55
W	00	O1	FF	O2	FF	O3	FF
O4	FF	O5	FF	O6	FF	O7	FF
O8	FF	O9	FF	OA	FF	OB	FF
OC	FF	OD	FF	Q0	FF	Q1	FF
Q2	FF	Q3	FF	Q4	FF	Q5	FF
Q6	FF	Q7	FF	Q8	FF	Q9	FF
QA	FF	QB	FF	QC	FF	QD	FF
QE	FF	QF	FF	T1	FF	T2	FF
T3	FF	T4	FF	T5	FF	T6	FF
T7	FF	T8	FF	T9	FF	TA	FF
TB	FF	TC	FF	TD	FF	TE	FF
TF	FF	P	22FF	H1	00	H2	00
1R	FF	2R	FF	3R	FF	4R	FF
5R	FF	6R	FF	7R	FF	8R	FF
9R	FF	AR	FF	BR	FF	CR	FF
DR	FF	ER	FF	FR	FF	1L	10
2L	FF	3L	FF	4L	FF	5L	10
6L	FF	7L	FF	8L	0F	9L	FF
AL	FF	BL	FF	CL	FF	DL	0F
EL	14	FL	FF	P1	05	P2	FF
P3	FF	P4	FF	P5	05	P6	FF
P7	FF	P8	05	P9	FF	PA	FF
PB	FF	PC	FF	PD	00	Z1	14
Z2	FF	Z3	FF	Z4	FF	Z5	FF
Z6	FF	Z7	FF	Z8	FF	Z9	FF


ZA	FF	ZB	FF	ZC	FF	ZD	FF
ZE	FF	ZF	FF	RR		H3	
H4		rr					



CONSULT-III plus Ver.23.31 Ver.CSP18.11
VIN:3N1CN7AP2CL[redacted]
Vehicle : VERSA Sedan N17 2012
Country : U.S.A.
Back
Home
Print Screen
Screen Capture
Measurement Mode
Recorded Data
Help
12.4V
VI
MI
Diagnosis (All Systems)
Select Vehicle
Confirm Vehicle
Diagnosis (All Systems)
AIR BAG
Self Diagnostic Result
Self Diagnosis [CAN]
Data Monitor
ECU Identification
TROUBLE DIAG RECORD
B1086 PRE-TEN FRONT LH [OPEN] CRNT - DTC Explanation
B1134 SIDE MODULE LH [OPEN] CRNT - DTC Explanation
B1150 CURTAIN MODULE LH [OPEN] CRNT - DTC Explanation
B1210 SIDE COLLISION DETECTION CRNT - DTC Explanation
1/1
Print
Save
ERASE



CONSULT-III plus Ver.23.31 Ver.CSP18.11
VIN:3N1CN7AP2CL[redacted]
Vehicle : VERSA Sedan N17 2012
Country : U.S.A.
Back
Home
Print Screen
Screen Capture
Measurement Mode
Recorded Data
Help
12.4V
VI
MI
Diagnosis (All Systems)
Select Vehicle
Confirm Vehicle
Diagnosis (All Systems)
AIR BAG
Self Diagnostic Result
Self Diagnosis [CAN]
Data Monitor
ECU Identification
TROUBLE DIAG RECORD
-
No DTC is detected.
Further testing may be required.
-
-
-
Print
Save



CONSULT-III plus Ver.23.31 Ver.CSP18.11
VIN:3N1CN7AP2CL[redacted]
Vehicle : VERSA Sedan N17 2012
Country : U.S.A.
Back
Home
Print Screen
Screen Capture
Measurement Mode
Recorded Data
Help
12.4V
VI
MI
Diagnosis (All Systems)
Select Vehicle
Confirm Vehicle
Diagnosis (All Systems)
AIR BAG
Self Diagnostic Result
Self Diagnosis [CAN]
Data Monitor
ECU Identification
TROUBLE DIAG RECORD
ECU DISCRIMINATED NO.
ff22



CONSULT-III plus Ver.23.31 Ver.CSP18.11
VIN:3N1CN7AP2C
Vehicle : VERSA Sedan N17 2012
Country : U.S.A.
Back
Home
Print Screen
Screen Capture
Measurement Mode
Recorded Data
Help
12.4V
VI
MI
Diagnosis (All Systems)
Select Vehicle
Confirm Vehicle
Diagnosis (All Systems)
AIR BAG
Self Diagnostic Result
Self Diagnosis [CAN]
Data Monitor
ECU Identification
TROUBLE DIAG RECORD
-
No DTC is detected.
Further testing may be required.
-
-
-
Print
Save



CONSULT-III plus Ver.23.31 Ver.CSP18.11
VIN:3N1CN7AP2C[redacted]
Vehicle : VERSA Sedan N17 2012
Country : U.S.A.
Back
Home
Print Screen
Screen Capture
Measurement Mode
Recorded Data
Help
12.4V
VI
MI
Diagnosis (All Systems)
Select Vehicle
Confirm Vehicle
Diagnosis (All Systems)
AIR BAG
Self Diagnosis [CAN]
Data Monitor
ECU Identification
TROUBLE DIAG RECORD
Cause of Warning Lamp
-
No DTC is detected.
Further testing may be required.
-
-
-
Print
Save


CONSULT-III plus Ver.23.31 Ver.CSP18.11
VIN:3N1CN7AP2CL[redacted]
Vehicle : VERSA Sedan N17 2012
Country : U.S.A.
Back
Home
Print Screen
Screen Capture
Measurement Mode
Recorded Data
Help
12.4V
VI
MI
Diagnosis (All Systems)
Select Vehicle
Confirm Vehicle
Diagnosis (All Systems)
AIR BAG
Self Diagnosis [CAN]
Data Monitor
ECU Identification
TROUBLE DIAG RECORD
Cause of Warning Lamp
AIR BAG
LOW VOLT TIME 0
IGN VOLT COND OK
LOW V RECORED 0
1 / 1


CONSULT-III plus Ver.23.31 Ver.CSP18.11
VIN:3N1CN7AP2C[redacted]
Vehicle : VERSA Sedan N17 2012
Country : U.S.A.
Back
Home
Print Screen
Screen Capture
Measurement Mode
Recorded Data
Help
12.4V
VI
MI
Diagnosis (All Systems)
Select Vehicle
Confirm Vehicle
Diagnosis (All Systems)
AIR BAG
Data Monitor
ECU Identification
TROUBLE DIAG RECORD
Cause of Warning Lamp
Special Function
Test Item
RECORDED DATA READOUT
EDR RECORDED DATA
1/1
Next


CONSULT-III plus Ver.23.31 Ver.CSP18.11
VIN:3N1CN7AP2C[redacted]
Vehicle : VERSA Sedan N17 2012
Country : U.S.A.
Back
Home
Print Screen
Screen Capture
Measurement Mode
Recorded Data
Help
12.4V
VI
MI
Diagnosis (All Systems)
Select Vehicle
Confirm Vehicle
Diagnosis (All Systems)
All DTC
CAN Diag
CAN DIAG SUPPORT MNTR
SRT & P-DTC
Result
AIR BAG CRNT
ABS PAST
BCM PAST
ENGINE NO DTC
METER/M&A NO DTC
TRANSMISSION NO DTC
EPS NO DTC
1/2
Detailed Information
AIR BAG
B1086 PRE-TEN FRONT LH [OPEN] CRNT - DTC Explan
B1134 SIDE MODULE LH [OPEN] CRNT - DTC Explan
B1150 CURTAIN MODULE LH [OPEN] CRNT - DTC Explan
B1210 SIDE COLLISION DETECTION CRNT - DTC Explan
ABS
C1116 STOP LAMP SW PAST FFD DTC Explan
BCM
C1705 LOW PRESSURE FR PAST - DTC Explan
1/2
Print for Customer
Print
Save
ERASE


CONSULT-III plus Ver.23.31 Ver.CSP18.11
VIN:3N1CN7AP2CL[redacted]
Vehicle : VERSA Sedan N17 2012
Country : U.S.A.
Back
Home
Print Screen
Screen Capture
Measurement Mode
Recorded Data
Help
12.4V
VI
MI
Diagnosis (All Systems)
Select Vehicle
Confirm Vehicle
Diagnosis (All Systems)
All DTC
CAN Diag
CAN DIAG SUPPORT MNTR
SRT & P-DTC
Result
AIR BAG CRNT
ABS PAST
BCM PAST
ENGINE NO DTC
METER/M&A NO DTC
TRANSMISSION NO DTC
EPS NO DTC
1/2
Detailed Information
C1706 LOW PRESSURE RR PAST - DTC Explan
C1710 [NO DATA] RR PAST - DTC Explan
2/2
Print for Customer
Print
Save
ERASE


CONSULT-III plus Ver.23.31 Ver.CSP18.11
VIN:3N1CN7AP2C[redacted]
Vehicle : VERSA Sedan N17 2012
Country : U.S.A.
Back
Home
Print Screen
Screen Capture
Measurement Mode
Recorded Data
Help
12.4V
VI
MI
Diagnosis (All Systems)
Select Vehicle
Confirm Vehicle
Diagnosis (All Systems)
All DTC
CAN Diag
CAN DIAG SUPPORT MNTR
SRT & P-DTC
Result
IPDM E/R
NO DTC
OCCUPANT DETECTION
No support for Self Diag
Detailed Information
C1706 LOW PRESSURE RR PAST - DTC Explan
C1710 [NO DATA] RR PAST - DTC Explan
2/2
2/2
Print for Customer
Print
Save
ERASE

EDR (Event Data Recorder) VERSA Sedan N17 /2012- 3N1CN7AP2C[redacted]

SYSTEM	AIR BAG
PART NUMBER	f122
VIN	3N1CN7AP2CL[redacted]

HIGH FREQUENCY DATA

FRONTAL DELTA-V

TIME	DATA
-100ms	0mph
-90ms	0mph
-80ms	0mph
-70ms	0mph
-60ms	0mph
-50ms	0mph
-40ms	0mph
-30ms	0mph
-20ms	0mph
-10ms	0mph
0ms	0mph
10ms	0mph
20ms	0mph
30ms	0mph
40ms	0mph
50ms	0mph
60ms	0mph
70ms	0mph
80ms	0mph
90ms	0mph
100ms	0mph
110ms	0mph
120ms	0mph
130ms	0mph
140ms	0mph
150ms	0mph
160ms	0mph
170ms	0mph
180ms	0mph
190ms	0mph
200ms	0mph
210ms	0mph
220ms	0mph
230ms	0mph
240ms	0mph
250ms	0mph
260ms	0mph
270ms	0mph
280ms	0mph
290ms	0mph
300ms	0mph

LATERAL DELTA-V

TIME	DATA
-100ms	0mph
-90ms	0mph
-80ms	0mph
-70ms	0mph
-60ms	0mph
-50ms	0mph
-40ms	0mph
-30ms	0mph
-20ms	0mph
-10ms	0mph
0ms	0mph
10ms	0mph
20ms	0mph
30ms	0mph
40ms	0mph
50ms	0mph
60ms	0mph
70ms	0mph
80ms	0mph
90ms	0mph
100ms	0mph
110ms	0mph
120ms	0mph
130ms	0mph
140ms	0mph
150ms	0mph
160ms	0mph
170ms	0mph
180ms	0mph
190ms	0mph
200ms	0mph
210ms	0mph
220ms	0mph
230ms	0mph
240ms	0mph
250ms	0mph
260ms	0mph
270ms	0mph
280ms	0mph
290ms	0mph
300ms	0mph

HIGH FREQUENCY DATA

FRONTAL G

TIME	DATA
-100ms	0.0G
-90ms	0.0G
-80ms	0.0G
-70ms	0.0G
-60ms	0.0G
-50ms	0.0G
-40ms	0.0G
-30ms	0.0G
-20ms	0.0G
-10ms	0.0G
0ms	0.6G
10ms	1.4G
20ms	-1.4G
30ms	-1.2G
40ms	0.4G
50ms	0.0G
60ms	-0.2G
70ms	0.2G
80ms	0.0G
90ms	0.0G
100ms	0.2G
110ms	0.0G
120ms	0.0G
130ms	0.0G
140ms	0.0G
150ms	0.0G
160ms	0.0G
170ms	0.0G
180ms	0.0G
190ms	-0.2G
200ms	0.0G
210ms	0.0G
220ms	0.0G
230ms	0.0G
240ms	0.0G
250ms	0.0G
260ms	0.0G
270ms	0.0G
280ms	0.0G
290ms	0.0G
300ms	0.0G

LATERAL G

TIME	DATA
-100ms	0.0G
-90ms	0.0G
-80ms	0.0G
-70ms	0.0G
-60ms	0.0G
-50ms	0.0G
-40ms	0.0G
-30ms	0.0G
-20ms	0.0G
-10ms	0.0G
0ms	-0.4G
10ms	2.6G
20ms	-1.6G
30ms	0.8G
40ms	-1.2G
50ms	1.4G
60ms	-0.4G
70ms	-0.2G
80ms	0.4G
90ms	0.0G
100ms	0.0G
110ms	0.0G
120ms	0.0G
130ms	0.0G
140ms	0.0G
150ms	0.0G
160ms	0.0G
170ms	0.0G
180ms	0.0G
190ms	0.0G
200ms	0.0G
210ms	0.0G
220ms	0.0G
230ms	0.0G
240ms	0.0G
250ms	0.0G
260ms	0.0G
270ms	0.0G
280ms	0.0G
290ms	0.0G
300ms	0.0G

Incident Investigation Report

CAR #: [redacted]
Claimant:
VIN: 3N1CN7AP2CL[redacted]

I. Claimant

Claimant name:	[redacted]		*DOB:*	[redacted]	*Day phone:* n/a
Address:		Milwaukee, WI, [redacted]			*Eve. Phone:* [redacted]
Driver Name			*DOB:*		*Day phone:*
Address:		Milwaukee, WI,			*Eve. Phone:*
Owner name:			*DOB:*		*Day phone:*
Address:		Milwaukee, WI,			*Eve. Phone:*

Who notified NNA of incident? Dealer SM called CA regarding C's allegation of air bag deployment without collision.

If represented, claimant's attorney name, address, phone: n/a

II. Vehicle

Model year & model name: 2012 Versa 1.6 SV Sedan *Mfg. date:* 8/8/11 *VIN:* 3N1CN7AP2CL[redacted]

Mileage: 26,407 *License #:* [redacted]Temp *State:* Wisconsin

Special equipment & accessories:
Accessory charger (see photos)
Accessory "patch" cable (see photos)

List all applicable recalls and service campaigns in table below:

Number	*Description*	*Status (Open/Closed)*
PM235	VERSA AT SHIFTER NTB12-008	Closed

III. Description of Incident & Claim

Source of information (unless otherwise noted): CA 9523768

Date & time of incident:: Date not specified in IIR probe
1:30 pm

Location of incident (describe fully):

n/a

Nature of weather: Mild, 50-60 temps, clear skies *Vision obstruction (describe):* n/a

Claimant's description of incident and statement of cause (be as detailed as possible):

- *Claimant's description of the "sequence of events" that occurred:*

C advised that sister-in-law had been driving c's veh, but had parked the veh and went inside the house, unsure how much time had elapsed, about 20 minutes, maybe. Heard a loud pop, thought a gun had been shot, looked outside, did not see anyone around, noticed airbags had deployed.

- *Relation to roadway (on-road, off-road, left side, right side):*

Parked on side of road.

- *Driver action (braking, steering, etc):*

n/a

- *Special circumstances:*

C stated no one in vehicle at time of deployment

Incident Investigation Report

CAR #: [redacted]
Claimant:
VIN: 3N1CN7AP2CL[redacted]

III. Description of Incident & Claim - continued

Vehicle estimated speed:	0	*Source of estimate:*	CA 9523768	*Posted speed limit:*	n/a
Other vehicle estimated speed:	n/a	*Source of estimate:*	n/a	*Posted speed limit:*	n/a

Name & address of witnesses:

n/a

Police report taken? (Yes/No/#): no

Reporting officer name & station (if report not attached): n/a

List each allegation made. Be as specific as possible and list affected components and detailed reasons for allegation.

#	Allegation	Allegation made by
1	Left-side curtain, seat and seat-belt pre-tensioner deployed while vehicle was parked and unoccupied.	[redacted]

IV. Occupants & Injuries

Location:	Seat Pos.	Seat Belts:	Air Bags:
n/a	n/a	n/a	n/a

Source of information: CA 9523768

Name: No-occupants *DOB:* n/a

Address: n/a *Height:* n/a *Weight:* n/a

Nature & extent of Injuries: n/a

Where, when, and by whom were the injured treated?

No occupants, no injuries, no treatment.

(Legend for Section IV.)

Location:	*1. Incident vehicle 2. Other Vehicle 3. Pedestrian 4. Other*
Seating Position:	 *10. Unknown 11. Other*
Seat Belts Worn:	*U. Unknown L. Lap Only S. Shoulder Only B. L+S belt N. None Worn C. Child Restraint*
Airbag Status:	*NA. Not equipped N. Airbag not deployed D. Airbag deployed*

V. Other Property Damage

Source of information (unless otherwise noted): n/a

Other vehicle model year, make, model name: n/a

Name, address, phone of other vehicle owner: n/a

Name, address, phone of other vehicle driver: n/a

Nature & extent of other vehicle damage: n/a

Nature & extent of property (other than motor vehicle) damage & name of owner:

n/a

Incident Investigation Report

CAR #: [redacted]
Claimant:
VIN: 3N1CN7AP2C[redacted]

VI. Investigation Results

Date of vehicle inspection: 10/23/12 *Location of inspection:* Rosen Nissan, Milwaukee WI

Nature & extent of damages to vehicle & estimated cost of repairs (Attach estimate if available):
Left-side curtain airbag, seat airbag, seatbelt, headliner, SRS control unit. No estimate availabe

Have you located any related prior repair orders? (Yes/No): no

Photos taken by: David Schend *# photos:* 138

Observations / findings. Be as detailed as possible, put "Not Available" in sections that you are not able to inspect. Include observations and findings from test drives and Consult diagnostics.

- *Exterior / Body:*

Damage on left front fender/bumper cover, left outside mirror cover (scuff), left-rear/rear bumper cover, right rear quarter panel ("door dings"), right front door (abrasion/scuff), front bumper cover (scuff/scratches). See photos.
Dent in lower left-front door jamb – no similar dent or other indication of contact present in mating surface of door. See photos.
No impact marks visible on left-front door jamb, latch, or striker. See photos.

- *Engine / Transmission / Drivetrain:*

Nothing unusual observed

- *Underbody / Suspension / Steering / Wheels & Tires:*

Right front hubcap scuffed and cracked - paint chipped from edge of wheel adjacent to hubcap damage. See photos
Minor cosmetic scrapes on remaining hubcaps.
No impact marks visible on underside of vehicle.

- *Interior Observations / Seats / Instrument Panel / Headliner / Trim:*

See photos.

- *Seat Belts / Child Restraints (if applicable):*

Left front seat-belt locked in retracted position.

- *Air Bags:*

Left-side curtain airbag deployed.
Left seat airbag deployed.

- *Additional Observations / Findings (describe any inspection items not covered under headings above, e.g. vehicle test drive with customer, site observations, etc.):*

See CONSULT information included in report.

- *Summary. List factual inspection findings pertaining to each allegation made by claimant. Ensure appropriate IIR supplements are filled out.*

#	Allegation	Factual Findings
1	Left-side curtain, seat and seat-belt pre-tensioner deployed while vehicle was parked and unoccupied.	Left-side curtain, seat and seat-belt pre-tensioner deployed. CONSULT III+ information included in report.

Have alleged defective parts been removed from vehicle? (Yes/No): no

If yes, by whom? n/a *Present location:* n/a

Incident Investigation Report

CAR #: [redacted]
Claimant:
VIN: 3N1CN7AP2CL[redacted]

Reporter's Signature: David Schend

Reporter's Name & Region: David Schend Nissan MWR

IIR Supplement: Restraint System Checklist

** On seat belt systems with more than one belt, buckle or retractor, please specify (e.g. Lap or Shoulder).*

DRIVER'S SEAT BELT*	
Model #:	Could not access label
Mfg. Date:	n/a
Lot #:	n/a
Manufacturer:	n/a
AS-FOUND CONDITION*	
Fully Stowed? (Yes/No):	Yes
If extended, measure webbing length from outboard floor anchor to D-ring:	n/a
Buckled? (Yes/No):	No
BUCKLE*	
Model #:	n/a
Buckle latches/unlatches (Yes/No):	n/a
RETRACTOR*	
Retractor(s) spring functioning? (Yes/No):	n/a
Retractor Locked? (Yes/No):	n/a
Emergency locking function operable? (Yes/No):	n/a
Describe how ELR was checked:	n/a

RF PASSENGER SEAT BELT*	
Model #:	n/a
Mfg. Date:	n/a
Lot #:	n/a
Manufacturer:	n/a
AS-FOUND CONDITION*	
Fully Stowed? (Yes/No):	n/a
If extended, measure webbing length from outboard floor anchor to D-ring:	n/a
Buckled? (Yes/No):	n/a
BUCKLE*	
Model #:	n/a
Buckle latches/unlatches (Yes/No):	n/a
RETRACTOR*	
Retractor(s) spring functioning? (Yes/No):	n/a
Retractor Locked? (Yes/No):	n/a
Auto locking (ALR) function operable? (Yes/No):	n/a
Emergency locking function operable? (Yes/No):	n/a
Describe how ELR was checked:	n/a

Incident Investigation Report

CAR #: [redacted]
Claimant:
VIN: 3N1CN7AP2C[redacted]

IIR Supplement: Restraint System Checklist (continued)

AIRBAG DEPLOYMENT INFORMATION

Driver "front" airbag deployed? (Yes/No):	No	*RF pass "front" airbag deployed? (Yes/No):*	No
Driver "side" airbag deployed? (Yes/No/NA):	Yes	*RF pass "side" airbag deployed? (Yes/No/NA):*	No
Left curtain airbag deployed? (Yes/No/NA):	Yes	*Right curtain airbag deployed? (Yes/No/NA):*	No

Airbag Warning Lamp Status *(when ignition is turned ON):*

	Illuminates for approximately 7 seconds and goes off (normal)
	Does not illuminate at all
X	*Remains illuminated continuously*
	Flashes continuously

Consult Data Included in Report (Yes/No)

DTCs (all items listed in below sub-menus)?	
○ Current DTCs	Yes
○ Past DTCs	Yes
○ Trouble Diag Record	Yes
Hexadecimal data?	**Yes**
EDR data (all items listed in below sub-menus)?	
○ All High-frequency data	**Yes**
○ All Low-frequency data	**Yes**
○ All Static Data	**Yes**

Always use diagnostic tool appropriate for vehicle. Photograph or scan Consult-II printout since thermal paper will degrade over time.

If any Consult data item above is marked as "No", please explain here why not included in report:

IIR Supplement: Restraint System Photograph Checklist

VIN plate (door jam)
Odometer
8 external views
Windshield (from standing in front of hood)
Exterior damage close-ups
Underbody views
(if possible and accident circumstances dictate)
Overhead view (if possible)
Engine compartment (hood open)
Engine compartment close-ups (hood open)
Front airbag sensors (where applicable)
Driver side open door view (angled forward)
Driver seat position
(perpendicular view documenting initial position)
Overview of drivers seating area (downward view)
Driver knee bolster area
Driver side upper instrument panel
Header and visor area
Headliner over driver and passenger seating area
Driver "front" airbag overall
Close-ups of any marks on driver "front" airbag

RF seatbelt - seatbelt label(s)
RF seatbelt - overall
RF seatbelt - webbing (any marks-note location)
RF seatbelt - latch plate metal (both sides)
RF seatbelt - latchplate pass through (both sides)
RF seatbelt - pillar guide loop (D-ring)
RF seatbelt - buckle (side view-inboard & outboard)
RF seatbelt - buckle (end view)

CASE BY CASE BASIS

LR seatbelt - seatbelt label(s)
LR seatbelt - overall
LR seatbelt - webbing (any marks-note location)
LR seatbelt - latchplate metal (both sides)
LR seatbelt - latchplate pass through (both sides)
LR seatbelt - pillar guide loop (D-ring)
LR seatbelt - buckle (side view-inboard & outboard)
LR seatbelt - buckle (end view)
CR seatbelt - seatbelt label(s)
CR seatbelt - overall
CR seatbelt - webbing (any marks-note location)

Incident Investigation Report

CAR #: [redacted]
Claimant:
VIN: 3N1CN7AP2CL[redacted]

Driver "front" airbag deployment door (upper)
Driver "front" airbag deployment door (lower)
Steering wheel rim side view
Passenger side open door view (angled forward)
RF seat position
(perpendicular view documenting initial position)
Overview of RF seating area (downward view)
RF knee bolster area
RF upper instrument panel
RF passenger "front" airbag overall
Close-ups of any marks on RF pass. "front" airbag
RF passenger "front" airbag deployment door
Driver "side" airbag
RF passenger "side" airbag
Left curtain airbag
Right curtain airbag

Drivers seatbelt - seatbelt label(s)
Drivers seatbelt – overall
Drivers seatbelt - webbing (any marks-note location)
Drivers seatbelt - latchplate metal (both sides)
Drivers seatbelt - latchplate pass thru (both sides)

Drivers seatbelt - pillar guide loop (D-ring)
Driver seatbelt - buckle (side view-inboard & outboard)
Drivers seatbelt - buckle (end view)

CR seatbelt - latchplate metal (both sides)
CR seatbelt - latchplate pass through (both sides)
CR seatbelt - buckle (side view-inboard & outboard)
CR seatbelt - buckle (end view)
RR seatbelt - seatbelt label(s)
RR seatbelt - overall
RR seatbelt - webbing (any marks-note location)
RR seatbelt - latchplate metal (both sides)
RR seatbelt - latchplate pass through (both sides)
RR seatbelt - pillar guide loop (D-ring)
RR seatbelt - buckle (side view-inboard & outboard)
RR seatbelt - buckle (end view)
Any visible prior damage (unrelated to subject accident)
Prior repairs to vehicle
Extrication/towing damage
Any non-OEM components (accessories, etc.)
Center console SRS diagnostic module (if necessary)













OP CODE	DESCRIPTION	OP CODE	DESCRIPTION	OP CODE	DESCRIPTION	OP CODE	DESCRIPTION
5NIZE	OIL CHANGE SER	9998	LUBE-OIL-GREAS	NPF	UNABLE TO DUPL	55NIZE	MULTI-POINT I
55NIZG	TIRE DEPTH 7/3						
78174WN	PM2530 REPLACE SHIFT	PW24AA	RPL LEFT FRONT	55NIZI	MULTI POINT VE	55NIZG	TIRE DEPTH 7/
812 115768746NE	55NIZE OIL CHANGE SER	9998	LUBE-OIL-GREAS	55NIZE	TIRE ROTATION	55NIZE	MULTI-POINT I
55NIZG	TIRE DEPTH 7/3						
320104NOV11 40408146NE	55NIZE LUBE OIL FILTE	9998	LUBE-OIL-GREAS	PM1650	ALIGNED OK	55NIZE	MULTI-POINT I
55NIZG	TIRE DEPTH 7/3						

WN ABOVE ARE THE MOST RECENT
VICES PERFORMED ON YOUR VEHICLE.

RRENT MILEAGE 26407

D ON THE CURRENT MILEAGE
OUR VEHICLE, THE MANUFAC-
R RECOMMENDS THAT THE
CES MARKED WITH AN 'X'
RFORMED NOW.

6M / 18M / 30M / 42M / 54M / 66M SVC	12M / 24M / 36M / 48M / 60M SVC	OIL AND FILTER CHANGES, LUBE & FLUIDS	SAFETY CHECK	SERVICE AIR CLEANER	SERVICE EMISSION CONTROL SYSTEM	SERVICE BATTERY AND CHARGING SYSTEM	ADJUST VALVES	SERVICE AUTOMATIC TRANSMISSION	REPLACE FUEL FILTER	ROTATE TIRES	WHEEL BALANCE	PACK FRONT WHEEL BEARINGS	FRONT END ALIGNMENT	INSPECT EXHAUST SYSTEM	INSPECT SHOCKS, SUSPENSION AND STEERING	INSPECT AIR SERVICE BRAKES	INSPECT AND ADJUST ALL BELTS	REPLACE WINDSHIELD WIPER BLADES	SERVICE WINDSHIELD WASHER SYSTEM	SCOPE AND SET DWELL	TUNE UP	CARBURETOR OVERHAUL	SERVICE AIR CONDITIONER	ADJUST PARKING BRAKE	INSPECT AND TEST ELECTRICAL SYSTEM	SERVICE DIFFERENTIAL	DRAIN AND FLUSH COOLING SYSTEM
X	X	X	X	X			X	X	X		X			X	X	X											

TUESDAY THURSDAY FRIDAY
8:00AM 5:00PM
MONDAY AND WEDNESDAY
8:00AM TILL 7:00PM

ROSEN NISSAN INC.
ROSEN KIA
5505 S. 27th STREET
GREENFIELD, WISCONSIN 53221
(414) 282-9300

YOU'LL COME FOR THE AFFORDABLE PRICES. YOU'LL BE BACK FOR THE SUPERIOR SERVICE!

Notice: You are entitled to inspect or receive any com
parts, or accessories replaced or removed by the shop.

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE
I hereby authorize the repair work herein set forth to be done along with the necessary material and agree
are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any oth
beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the su
transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on
highway
acknow
shown.
X

NO333162 STOCK NO. [redacted] TAG NO. T982 COLOR MAGNETIC GRAY PAGE 1 OF

TE	VEHICLE IDENTIFICATION NUMBER	MILEAGE	DELIVER DATE	LICENSE NUMBER	YEAR	MAKE AND MODEL	WRITTEN BY	RO NU
P2012	3N1CN7AP2CL[redacted]	26407	08SEP11		12	NISSAN VERSA 1.6	7487	[redacted]

L WORK AUTHORIZED BY X: _____ NAME _____

TIME A.M. P.M. NO. CALLED NEW TOTAL ESTIMATE

DATE TIME BY

NAME [redacted] Tuesday 23

615-725-7211

TIME PROMISE
** WAITER

CITY/STATE/ZIP
MILWAUKEE WI [redacted]

HOME PHO [redacted]

BILL TO:

P.O. NO.

BUSINESS PH

ENGINE NO. 1.6 Liter

TRANSM. NO. A

AXLE NO.

PROD. DATE

case #
[redacted]

Tom [illegible]7261 #7

METHOD OF PAYMENT

SELLING DEALER

9.95 5 of 7

E A PRICE ESTIMATE FOR THE REPAIRS YOU HAVE AUTHORIZED. IF THE ESTIMATE WILL NOT EXCEED THE AMOUNT, YOUR SIGNATURE WILL INDICATE YOU

E ESTIMATE IN WRITING BEFORE YOU BEGIN REPAIRS _____

SED WITH REPAIRS, BUT CALL ME BEFORE CONTINUING IF THE PRICE WILL

T AN ESTIMATE _____

E RECEIVED WITHOUT FACE TO FACE CUSTOMER CONTACT

HE AUTHORIZED REPAIRS WILL NOT BE EXCEEDED IF THE MOTOR
ERED TO THE SHOP WITHIN 5 DAYS

PROCEED WITH REPAIRS, BUT CALL ME BEFORE CONTINUING IF THE PRICE WILL

DO NOT WANT AN ESTIMATE

THIS VEHICLE RECEIVED WITHOUT FACE TO FACE CUSTOMER CONTACT.

PRICE FOR THE AUTHORIZED REPAIRS WILL NOT BE EXCEEDED IF THE MOTOR VEHICLE IS DELIVERED TO THE SHOP WITHIN 5 DAYS.

DO YOU WANT THE REPLACEMENT PARTS YOU ARE ENTITLED TO?
☐ YES ☐ NO

BILL TO:

ENGINE NO.	TRANSM. NO.	AXLE NO.	PROD. DATE
1.6 Liter	A		

Tom
800-647-7261 #7
x 457378

case #
[redacted]

METHOD OF PAYMENT
SECOND DEALER
WARRANTY EXPIRES

NE	OP CODE	LABOR INSTRUCTIONS AND DESCRIPTION
A	55NIZELOF	OIL CHANGE SERVICE & T.C rotation
B	55NIZEINSP	MULTI-POINT INSPECTION
C		C/S AIR BAG DEPLOYED WIHLE DRIVING
		C/S TPMS SENSOR [redacted] ON
		Air filter replaced.

800-647-7261

QTS. OIL
LBS. GREASE
GA. GAS
QTS. TRANS.
| | CASH

TOWING

MISC. CHARGES


No re

SUBLETS
P.O.NO.

vehicle repair practices are regulated
ter ATCP 132, Wis. Adm. Code,
ted by the Bureau of Consumer
, Wisconsin Dept. of Agriculture,
r Consumer Protection, P.O. Box
dison, Wisconsin 53708-8911."

SERVICE ADVISOR'S SIGNATURE X

TECHNICIAN COPY



OP CODE	DESCRIPTION	OP CODE	DESCRIPTION
5NIZE	OIL CHANGE SER9998	NABLE TO DUPL	55NIZE MULTI-POINT IN
5NIZG	TIRE DEPTH 7/3		
/4WNPM2530	REPLACE SHIFT PW24AA RPL	21 MULTI POINT VE	55NIZG TIRE DEPTH 7/3
812 115768746NE	55NIZE OIL CHANGE SER9998	LUBE-OI	NIZE TIRE ROTATION 55NIZE MULTI-POINT IN
	55NIZG TIRE DEPTH 7/3		
67320104NOV11 40408146NE	55NIZE LUBE OIL FILTE9998	LUBE-OIL-GREASPM1650	ALIGNED OK 55NIZE MULTI-POINT IN
	55NIZG TIRE DEPTH 7/3		

SHOWN ABOVE ARE THE MOST RECENT SERVICES PERFORMED ON YOUR VEHICLE.

CURRENT MILEAGE 26407

BASED ON THE CURRENT MILEAGE OF YOUR VEHICLE, THE MANUFACTURER RECOMMENDS THAT THE SERVICES MARKED WITH AN 'X' BE PERFORMED NOW.

6M / 10M	12M / 18M	24M / 30M	36M / 42M	48M / 54M	60M / 66M	72M / 78M	84M / 90M	OIL AND FILTER CHANGE, LUBE & PLUGS	DAILY CHECK	SERVICE AIR CLEANER	SERVICE EMISSION CONTROL SYSTEM	SERVICE BATTERY AND CHARGING SYSTEM	ADJUST VALVES	SERVICE AUTOMATIC TRANSMISSION	REPLACE FUEL FILTER	ROTATE TIRES	WHEEL BALANCE	PACK FRONT WHEEL BEARINGS	FRONT END ALIGNMENT	INSPECT EXHAUST SYSTEM	INSPECT SHOCKS, SUSPENSION, AND STEERING	INSPECT AND SERVICE BRAKES	INSPECT AND ADJUST ALL BELTS	SERVICE WINDSHIELD WIPER BLADES	CLEAN AND SET SPARK PLUGS	TUNE UP	CARBURETOR OVERHAUL	SERVICE AIR CONDITIONER	ADJUST PARKING BRAKE	INSPECT AND TEST ELECTRICAL SYSTEM	SERVICE DIFFERENTIAL	DRAIN AND FLUSH COOLING SYSTEM
X	X	X	X	X				X	X	X		X		X	X	X															

TUESDAY, THURSDAY, FRIDAY
8:00AM TO 5:00PM
MONDAY AND WEDNESDAY
8:00AM TO 7:00PM

Notice: You are entitled to inspect or receive any compl... parts, or accessories replaced or removed by the shop.

ROSEN NISSAN INC.
ROSEN KIA
5505 S. 27th STREET
GREENFIELD, WISCONSIN 53221
(414) 282-9300

YOU'LL COME FOR THE AFFORDABLE PRICES. YOU'LL BE BACK FOR THE SUPERIOR SERVICE!

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE
I hereby authorize the repair work herein set forth to be done along with the necessary material and agree th... are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any othe... beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the su... transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on ... highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is ... acknowledge... to. I accept the terms of the war... shown. Ro... Rosen is required to seek enforcem...
X [redacted]

CUST. NO [redacted] STOCK NO. [redacted] TAG NO. T982 COLOR MAGNETIC GRAY PAGE 1 OF

DATE	VEHICLE IDENTIFICATION NUMBER	MILEAGE	DELIVER DATE	LICENSE NUMBER	YEAR	MAKE AND MODEL	WRITTEN BY	RO NU
27SEP2012	3N1CN7AP2CL[redacted]	26407	08SEP11		12	NISSAN VERSA 1.6	7487	[redacted]

ADDITIONAL WORK AUTHORIZED BY X: _____ NAME _____
DATE TIME A.M. P.M. NO. CALLED NEW TOTAL ESTIMATE

REVISED ESTIMATE (2) DATE TIME BY

YOU ARE ENTITLED TO A PRICE ESTIMATE FOR THE REPAIRS YOU HAVE AUTHORIZED. ... BE USED. THE ESTIMATE ... WILL NOT EXCEED THE ESTIMATE ... YOUR SIGNATURE WILL INDICATE YOU

1. REQUEST AN ESTIMATE IN WRITING BEFORE YOU BEGIN REPAIRS _____
2. PROCEED WITH REPAIRS, BUT CALL ME BEFORE CONTINUING IF THE PRICE WILL ... _____
3. I DO NOT WANT AN ESTIMATE _____
4. THIS VEHICLE RECEIVED WITHOUT FACE TO FACE CUSTOMER CONTACT.

THIS PRICE FOR THE AUTHORIZED REPAIRS WILL NOT BE EXCEEDED IF THE MOTOR VEHICLE IS DELIVERED TO THE SHOP WITHIN 5 DAYS.

DO YOU WANT THE REPLACEMENT PARTS YOU ARE ENTITLED TO?
☐ YES ☐ NO

NAME [redacted]
Tuesday 23
615-725-7211

CITY/STATE/ZIP MILWAUKEE WI [redacted]

BILL TO: P.O. NO.

ENGINE NO. 1.6 Liter TRANSM. NO. A AXLE NO. PROD. DATE

Tom 800-647-7261 #7 x 457378

case# [redacted]

TIME PROMISED ** WAITER

HOME PHONE [redacted]

BUSINESS PH...

METHOD OF PAYMENT
SELLING DEALER
WARRANTY EXPIRES

LINE	OP CODE	LABOR INSTRUCTIONS AND DESCRIPTION
A	55NIZELOF	OIL CHANGE SERVICE

QTS. OIL
LBS. GREASE

NUFACTURED BY NISSAN MOTOR CO., LTD.
E: 08/11. GVWR: 3388 LBS
R FR: 1750 LBS GAWR RR: 1671 LBS
THIS VEHICLE CONFORMS TO ALL APPLICABLE FEDERAL MOTOR VEHICLE SAFETY, BUMPER AND THEFT PREVENTION STANDARDS IN EFFECT ON THE DATE OF MANUFACTURE SHOWN ABOVE.
SEE OWNER'S MANUAL FOR ADDITIONAL INFORMATION.
N: 3N1CN7AP2CL[redacted] PASSENGER CAR.

LOR	TRIM	TRANS	AXLE	ENGINE
[redacted]	G	REOF11A	GM38	HR16DE 1598 CC

DEL: BDTALBZ-EUA 4Z000




ODO
26407
H
C
1
1/2
0
40
20


ROSEN
ROSEN
ROSEN
www.rosenrosenrosen.com




TAGE


NISSAN TIRE ADVANTAGE
ROSEN
ROSEN


VERSA
SV
ROSEN
www.rosenrosenrosen.com




TIRE SALES EVENT








VERSA
ROSEN
www.rosenrosenrosen.com
































20


20







NISSAN
























AIRBAG


P618663301AA03
L
Y2A16TSDAGD
LG2B LH


P618663301AA03
Y2A16TSDAGD
L
LH















GOLD








GUIDO
GUIDO

ecco














U2617VSEATY
SAN L02B LH


SAN L02B LH


*P6185




$1.99


$1.99


$1.99






R
L








SAFETY INTRUCTIONS




























NISSAN
"Where you save a fistful of dollars"
ROSEN
ROSEN
ROSEN
www.rosenrosenrosen.com
www.rosenrosenrosen.com


ROSEN

Walgreens
$1.99



W.A.S.P.



NOK-6101






MOOR FOOD





CONSULT-III plus Ver.23.31 Ver.CSP18.11
VIN:3N1CN7AP2CL[redacted]
Vehicle : VERSA Sedan N17 2012
Country : U.S.A.
Back
Home
Print Screen
Screen Capture
Measurement Mode
Recorded Data
Help
12.4V
VI
MI
Diagnosis (All Systems)
Select Vehicle
Confirm Vehicle
Diagnosis (All Systems)
AIR BAG
Self Diagnostic Result
Self Diagnosis [CAN]
Data Monitor
ECU Identification
TROUBLE DIAG RECORD
B1086 PRE-TEN FRONT LH [OPEN] CRNT - DTC Explanation
B1134 SIDE MODULE LH [OPEN] CRNT - DTC Explanation
B1150 CURTAIN MODULE LH [OPEN] CRNT - DTC Explanation
B1210 SIDE COLLISION DETECTION CRNT - DTC Explanation
1/1
Print
Save
ERASE


CONSULT-III plus Ver.23.31 Ver.CSP18.11
VIN:3N1CN7AP2CL[redacted]
Vehicle : VERSA Sedan N17 2012
Country : U.S.A.
Back
Home
Print Screen
Screen Capture
Measurement Mode
Recorded Data
Help
12.4V
VI
MI
Diagnosis (All Systems)
Select Vehicle
Confirm Vehicle
Diagnosis (All Systems)
AIR BAG
Self Diagnostic Result
Self Diagnosis [CAN]
Data Monitor
ECU Identification
TROUBLE DIAG RECORD
-
No DTC is detected.
Further testing may be required.
-
-
-
Print
Save


CONSULT-III plus Ver.23.31 Ver.CSP18.11
VIN:3N1CN7AP2C
Vehicle : VERSA Sedan N17 2012
Country : U.S.A.
Back
Home
Print Screen
Screen Capture
Measurement Mode
Recorded Data
Help
12.4V
VI
MI
Diagnosis (All Systems)
Select Vehicle
Confirm Vehicle
Diagnosis (All Systems)
AIR BAG
Self Diagnostic Result
Self Diagnosis [CAN]
Data Monitor
ECU Identification
TROUBLE DIAG RECORD
ECU DISCRIMINATED NO.
ff22


CONSULT-III plus Ver.23.31 Ver.CSP18.11
VIN:3N1CN7AP2CL
Vehicle : VERSA Sedan N17 2012
Country : U.S.A.
Back
Home
Print Screen
Screen Capture
Measurement Mode
Recorded Data
Help
12.5V
VI
MI
Diagnosis (All Systems)
Select Vehicle
Confirm Vehicle
Diagnosis (All Systems)
AIR BAG
Self Diagnosis [CAN]
Data Monitor
ECU Identification
TROUBLE DIAG RECORD
Cause of Warning Lamp
No DTC is detected.
Further testing may be required.
Print
Save


CONSULT-III plus Ver.23.31 Ver.CSP16.11
VIN:3N1CN7AP2CL[redacted]
Vehicle : VERSA Sedan N17 2012
Country : U.S.A.
Back
Home
Print Screen
Screen Capture
Measurement Mode
Recorded Data
Help
12.4V
VI
MI
Diagnosis (All Systems)
Select Vehicle
Confirm Vehicle
Diagnosis (All Systems)
AIR BAG
Self Diagnosis [CAN]
Data Monitor
ECU Identification
TROUBLE DIAG RECORD
Cause of Warning Lamp
AIR BAG
LOW VOLT TIME 0
IGN VOLT COND OK
LOW V RECORED 0
1/1
































3N1CN7AP2CL8
NISSAN





PE16-013

NISSAN

11-16-2016

ATTACHMENT B

Request TWO Supporting Documents

Field Reports

3N1CN7AP2CL[redacted]

EDR (Event Data Recorder) VERSA Sedan N17 /2012- 3N1CN7AP2CL[redacted]

SYSTEM	AIR BAG
PART NUMBER	ff22
VIN	3N1CN7AP2CL[redacted]

HIGH FREQUENCY DATA

FRONTAL DELTA-V

TIME	DATA
-100ms	0mph
-90ms	0mph
-80ms	0mph
-70ms	0mph
-60ms	0mph
-50ms	0mph
-40ms	0mph
-30ms	0mph
-20ms	0mph
-10ms	0mph
0ms	0mph
10ms	0mph
20ms	0mph
30ms	0mph
40ms	0mph
50ms	0mph
60ms	0mph
70ms	0mph
80ms	0mph
90ms	0mph
100ms	0mph
110ms	0mph
120ms	0mph
130ms	0mph
140ms	0mph
150ms	0mph
160ms	0mph
170ms	0mph
180ms	0mph
190ms	0mph
200ms	0mph
210ms	0mph
220ms	0mph
230ms	0mph
240ms	0mph
250ms	0mph
260ms	0mph
270ms	0mph
280ms	0mph
290ms	0mph
300ms	0mph

LATERAL DELTA-V

TIME	DATA
-100ms	0mph
-90ms	0mph
-80ms	0mph
-70ms	0mph
-60ms	0mph
-50ms	0mph
-40ms	0mph
-30ms	0mph
-20ms	0mph
-10ms	0mph
0ms	0mph
10ms	0mph
20ms	0mph
30ms	0mph
40ms	0mph
50ms	0mph
60ms	0mph
70ms	0mph
80ms	0mph
90ms	0mph
100ms	0mph
110ms	0mph
120ms	0mph
130ms	0mph
140ms	0mph
150ms	0mph
160ms	0mph
170ms	0mph
180ms	0mph
190ms	0mph
200ms	0mph
210ms	0mph
220ms	0mph
230ms	0mph
240ms	0mph
250ms	0mph
260ms	0mph
270ms	0mph
280ms	0mph
290ms	0mph
300ms	0mph

Generated by CamScanner

EDR (Event Data Recorder) VERSA Sedan N17 /2012- 3N1CN7AP2CL[redacted]

HIGH FREQUENCY DATA

FRONTAL G

TIME	DATA
-100ms	0.0G
-90ms	0.0G
-80ms	0.0G
-70ms	0.0G
-60ms	0.0G
-50ms	0.0G
-40ms	0.0G
-30ms	0.0G
-20ms	0.0G
-10ms	0.0G
0ms	-1.6G
10ms	-1.2G
20ms	1.8G
30ms	0.8G
40ms	-0.8G
50ms	0.4G
60ms	0.2G
70ms	0.0G
80ms	0.0G
90ms	0.0G
100ms	0.0G
110ms	0.2G
120ms	0.0G
130ms	0.0G
140ms	0.0G
150ms	0.0G
160ms	0.0G
170ms	0.0G
180ms	0.0G
190ms	0.0G
200ms	0.0G
210ms	0.0G
220ms	0.0G
230ms	0.0G
240ms	0.0G
250ms	0.0G
260ms	0.0G
270ms	0.0G
280ms	0.0G
290ms	0.0G
300ms	0.0G

LATERAL G

TIME	DATA
-100ms	0.0G
-90ms	0.0G
-80ms	0.0G
-70ms	0.0G
-60ms	0.0G
-50ms	0.0G
-40ms	0.0G
-30ms	0.0G
-20ms	0.0G
-10ms	0.0G
0ms	1.0G
10ms	-1.2G
20ms	1.4G
30ms	0.6G
40ms	0.0G
50ms	0.0G
60ms	-0.2G
70ms	0.0G
80ms	0.8G
90ms	0.4G
100ms	0.0G
110ms	0.2G
120ms	0.0G
130ms	0.2G
140ms	0.0G
150ms	0.0G
160ms	0.0G
170ms	0.0G
180ms	0.0G
190ms	0.0G
200ms	0.0G
210ms	0.0G
220ms	0.0G
230ms	0.0G
240ms	0.0G
250ms	0.0G
260ms	0.0G
270ms	0.0G
280ms	0.0G
290ms	0.0G
300ms	0.0G

Generated by CamScanner

EDR (Event Data Recorder) VERSA Sedan N17 /2012- 3N1CN7AP2CL[redacted]

LOW FREQUENCY DATA

VEHICLE SPEED

TIME	DATA
-7s	0mph
-6s	0mph
-5s	0mph
-4s	0mph
-3s	0mph
-2s	0mph
-1s	0mph
0s	0mph
1s	0mph
2s	0mph
3s	0mph
4s	0mph
5s	0mph
6s	0mph

ENGINE REVOLUTION

TIME	DATA
-7s	737rpm
-6s	743rpm
-5s	728rpm
-4s	725rpm
-3s	725rpm
-2s	725rpm
-1s	728rpm
0s	715rpm
1s	706rpm
2s	703rpm
3s	700rpm
4s	690rpm
5s	690rpm
6s	681rpm

Generated by CamScanner

EDR (Event Data Recorder) VERSA Sedan N17 /2012- 3N1CN7AP2C[redacted]

LOW FREQUENCY DATA

THROTTLE PEDAL POSITION

TIME	DATA
-7s	0%
-6s	0%
-5s	0%
-4s	0%
-3s	0%
-2s	0%
-1s	0%
0s	0%
1s	0%
2s	0%
3s	0%
4s	0%
5s	0%
6s	0%

STEERING ANGLE

TIME	DATA
-7s	351deg
-6s	351deg
-5s	351deg
-4s	351deg
-3s	351deg
-2s	351deg
-1s	351deg
0s	352deg
1s	352deg
2s	352deg
3s	352deg
4s	352deg
5s	358deg
6s	359deg

Generated by CamScanner

EDR (Event Data Recorder) VERSA Sedan N17 /2012- 3N1CN7AP2C[redacted]

LOW FREQUENCY DATA

BRAKE PEDAL SW STATE

TIME	DATA
-7s	Off
-6s	Off
-5s	Off
-4s	Off
-3s	Off
-2s	Off
-1s	Off
0s	Off
1s	Off
2s	Off
3s	Off
4s	Off
5s	Off
6s	Off

GEAR POSITION

TIME	DATA
-7s	PorN
-6s	PorN
-5s	PorN
-4s	PorN
-3s	PorN
-2s	PorN
-1s	PorN
0s	PorN
1s	PorN
2s	PorN
3s	PorN
4s	PorN
5s	PorN
6s	PorN

Generated by CamScanner

EDR (Event Data Recorder) VERSA Sedan N17 /2012- 3N1CN7AP2CL[redacted]

LOW FREQUENCY DATA

BUCKLE SW STATE[DR]

TIME	DATA
-7s	Off
-6s	Off
-5s	Off
-4s	Off
-3s	Off
-2s	Off
-1s	Off

BUCKLE SW STATE[AS]

TIME	DATA
-7s	Off
-6s	Off
-5s	Off
-4s	Off
-3s	Off
-2s	Off
-1s	Off

Generated by CamScanner

EDR (Event Data Recorder) VERSA Sedan N17 /2012- 3N1CN7AP2CL[redacted]

LOW FREQUENCY DATA

DIAGMUXON STATE

TIME	DATA
-7s	On
-6s	On
-5s	On
-4s	On
-3s	On
-2s	On
-1s	On
0s	On
1s	On
2s	On
3s	On
4s	On
5s	On
6s	On

Generated by CamScanner

EDR (Event Data Recorder) VERSA Sedan N17 /2012- 3N1CN7AP2CL[redacted]

STATIC DATA

MAX.FRONTAL G&TIME

	FRONTAL	TIME
	4.0G	13ms

MAX.LATERAL G&TIME

	FRONTAL	TIME
	5.2G	23ms

Generated by CamScanner

EDR (Event Data Recorder) VERSA Sedan N17 /2012- 3N1CN7AP2CL[redacted]

STATIC DATA

A/B W/L STATE

	STATE	
	Off	

IGN CYCLE

		CYCLE
	Event	1561count
	Download	3618count

Generated by CamScanner

EDR (Event Data Recorder) VERSA Sedan N17 /2012- 3N1CN7AP2CL[redacted]

STATIC DATA

EDR RECORDING COMPLETE

	STATE	
Priority 1	SUCCESS	
Priority 2	SUCCESS	
Priority 3	SUCCESS	
Priority 4	SUCCESS	

GAP TIME FOR EDR

		TIME
	High Freq	2count
	Low Freq	91count

Generated by CamScanner

EDR (Event Data Recorder) VERSA Sedan N17 /2012- 3N1CN7AP2CL[redacted]

STATIC DATA

OPERATION TIME

		TIME
	Event	520hour
	Download	1012hour

D/L COUNT AFTER EVENT

	STATE	
	1count	

Generated by CamScanner

EDR (Event Data Recorder) VERSA Sedan N17 /2012- 3N1CN7AP2CL[redacted]

STATIC DATA

CAN ABNORMALITY

	STATE	
	NORMAL	

Generated by CamScanner

Load Data VERSA Sedan N17 /2012- 3N1CN7AP2CL[redacted]

SYSTEM	AIR BAG
PART NUMBER	ff22
VIN	3N1CN7AP2CL[redacted]

f	00	r	01	a0	00D2	a1	0081
a2	0051	a3	0091	a4	0000	a5	0000
a6	0000	a7	0000	a8	0000	a9	0000
aa	0000	ab	0000	ac	0000	ad	0000
ae	0000	af	0000	A1	0000	A2	0000
A3	0000	A4	0000	A5	0000	B1	0000
B2	0000	B3	0000	B4	0000	B5	0000
C1	0000	C2	0000	C3	0000	C4	0000
C5	0000	D1	0000	D2	0000	D3	0000
D4	0000	D5	0000	E1	0000	E2	0000
E3	0000	E4	0000	E5	0000	F1	00
F2	00	G	00	U	0C	I1	FF
J1	FF	K1	FF	L1	04	M1	FF
I2	FF	J2	FF	K2	FF	L2	FF
M2	00	IR	04	JR	03	KR	01
LR	FF	MR	03	IL	FF	JL	FF
KL	01	LL	FF	ML	FF	R	08
S1	55	S2	55	S3	55	S4	8C
S5	8C	S6	8E	S7	8E	S8	55
W	00	O1	FF	O2	FF	O3	FF
O4	FF	O5	FF	O6	FF	O7	FF
O8	FF	O9	FF	OA	FF	OB	FF
OC	FF	OD	FF	Q0	FF	Q1	FF
Q2	FF	Q3	FF	Q4	FF	Q5	FF
Q6	FF	Q7	FF	Q8	FF	Q9	FF
QA	FF	QB	FF	QC	FF	QD	FF
QE	FF	QF	FF	T1	FF	T2	FF
T3	FF	T4	FF	T5	FF	T6	FF
T7	FF	T8	FF	T9	FF	TA	FF
TB	FF	TC	FF	TD	FF	TE	FF
TF	FF	P	FF22	H1	00	H2	00
1R	FF	2R	FF	3R	FF	4R	FF
5R	FF	6R	FF	7R	FF	8R	FF
9R	FF	AR	FF	BR	FF	CR	FF
DR	FF	ER	FF	FR	FF	1L	04
2L	FF	3L	FF	4L	02	5L	04
6L	FF	7L	FF	8L	04	9L	FF
AL	FF	BL	FF	CL	FF	DL	00
EL	FF	FL	FF	P1	12	P2	FF
P3	FF	P4	FF	P5	12	P6	FF
P7	FF	P8	12	P9	FF	PA	FF
PB	FF	PC	FF	PD	0C	Z1	FF
Z2	FF	Z3	FF	Z4	FF	Z5	FF
Z6	FF	Z7	FF	Z8	FF	Z9	FF

Generated by CamScanner

Load Data VERSA Sedan N17 /2012- 3N1CN7AP2CL[redacted]

ZA	FF	ZB	FF	ZC	FF	ZD	FF
ZE	FF	ZF	FF	RR		H3	
H4		rr					

Generated by CamScanner

Self Diagnosis Result | VERSA Sedan | N17 | /2012- | 3N1CN7AP2CL[redacted]

SYSTEM	PART NUMBER	DTC	Detailed Information	TIME
METER/M&A		No DTC		

Generated by CamScanner

Self Diagnosis Result　VERSA Sedan　N17　/2012-　3N1CN7AP2CL[redacted]

SYSTEM	PART NUMBER	DTC	Detailed Information	TIME
ENGINE	23710-3AB3A	No DTC		

Generated by CamScanner

Self Diagnosis Result VERSA Sedan N17 /2012- 3N1CN7AP2CL[redacted]


SYSTEM	PART NUMBER	DTC	Detailed Information	TIME
ABS	47660-3BA2B	No DTC		

Generated by CamScanner

Self Diagnosis Result VERSA Sedan N17 /2012- 3N1CN7AP2CL[redacted]

SYSTEM	PART NUMBER	DTC	Detailed Information	TIME
TRANSMISSION	31036-3AA6A	P0846	FLUID PRESS SEN/SW B	PAST

Generated by CamScanner



AIR BAG

LOW VOLT TIME	0	
IGN VOLT COND	OK	
LOW V RECORED	0	

1 / 1

Generated by CamScanner

Self Diagnosis Result-CAN | VERSA Sedan | N17 | /2012- | 3N1CN7AP2CL[redacted]


SYSTEM	PART NUMBER	DTC	Detailed Information	TIME
AIR BAG	ff22	No DTC		

Generated by CamScanner

Self Diagnosis Result History VERSA Sedan N17 /2012- 3N1CN7AP2C[redacted]

SYSTEM	PART NUMBER	DTC	Detailed Information	TIME
AIR BAG	ff22	No DTC		

Generated by CamScanner



Generated by CamScanner

All Self Diagnosis Results VERSA Sedan N17 /2012- 3N1CN7AP2CL[redacted]

SYSTEM	PART NUMBER	DTC	Detailed Information	TIME
AIR BAG	ff22	B1081	PRE-TEN FRONT RH [OPEN]	CRNT
AIR BAG	ff22	B1129	SIDE MODULE RH [OPEN]	CRNT
AIR BAG	ff22	B1145	CURTAIN MODULE RH [OPEN]	CRNT
AIR BAG	ff22	B1210	SIDE COLLISION DETECTION	CRNT
TRANSMISSION	31036-3AA6A	P0846	FLUID PRESS SEN/SW B	PAST
ENGINE	23710-3AB3A	No DTC		
ABS	47660-3BA2B	No DTC		
METER/M&A		No DTC		
BCM	284B2-3AN1A	No DTC		
EPS/DAST 3	28500-3AN0A	No DTC		
IPDM E/R	284B7-1HA0A	No DTC		

Generated by CamScanner

Incident Investigation Report

CAR #: [redacted]
Claimant: [redacted]
VIN: 3N1CN7AP2CL[redacted]23N1C
N7AP2CL[redacted]

I. Claimant

Claimant name: [redacted] *DOB:* [redacted] *Day phone:* [redacted]

Address: [redacted] Scribner, NE [redacted] *Eve. Phone:*

Driver Name [redacted] *DOB:* *Day phone:*

Address: [redacted]t, Scribner, NE, [redacted] *Eve. Phone:*

Owner name: [redacted] *DOB:* *Day phone:*

Address: [redacted], Scribner, NE, [redacted] *Eve. Phone:*

Who notified NNA of incident? Owner

If represented, claimant's attorney name, address, phone:

N/A

II. Vehicle

Model year & model name: 2012 Versa Sedan *Mfg. date:* 9/11 *VIN:* 3N1CN7AP2CL[redacted]

Mileage: 71344 *License* [redacted] *State:* NE

Special equipment & accessories: None

List all applicable recalls and service campaigns in table below:

Number	*Description*	*Status (Open/Closed)*
N/A	N/A	N/A
N/A	N/A	N/A
N/A	N/A	N/A
N/A	N/A	N/A
N/A	N/A	N/A

III. Description of Incident & Claim

Source of information (unless otherwise noted): CA file and IIR Probe

Date & time of incident:: 12.3.13

Location of incident (describe fully):

Customer parked at curb in front of their house, vehicle had been sitting for about 6hrs.

Nature of weather Overcast in the 30's *Vision obstruction (describe):* None

Claimant's description of incident and statement of cause (be as detailed as possible):

Customer parked at curb in front of their house, vehicle had been sitting for about 6hrs. Cust got in and started vehicle and sat in vehicle for about 10 mins. Husband opened the passenger door and realized he forgot something and slammed the door to go back inside the house, when passenger side curtain airbag and side airbag deployed. Customers 6yr old son was sitting in passenger seat waiting on dad to return, no injuries.

- *Relation to roadway (on-road, off-road, left side, right side):*

On the road in front of customers house.

- *Driver action (braking, steering, etc):*

In park sitting at idle.

- *Special circumstances:*

Incident Investigation Report

None

Incident Investigation Report

CAR #:
Claimant: [redacted]
VIN: 3N1CN7AP2C[redacted]

III. Description of Incident & Claim - continued

Vehicle estimated speed: 0mph
Source of estimate: Customer
Posted speed limit: N/A

Other vehicle estimated speed: N/A
Source of estimate: Customer
Posted speed limit: N/A

Name & address of witnesses:

N/A

Police report taken? (Yes/No/#) NO

Reporting officer name & station (if report not attached): N/A

List each allegation made. Be as specific as possible and list affected components and detailed reasons for allegation.

#	Allegation	Allegation made by
1	Unwarranted Airbag Deployment	Cust
2	N/A	N/A
3	N/A	N/A
4	N/A	N/A
5	N/A	N/A

IV. Occupants & Injuries

Source of information: IIR Probe

Location:	Seat Pos.	Seat Belts:	Air Bags:	
1	1	U	N	*Nature & extent of Injuries:* None

Name: [redacted]
DOB: [redacted]
Address: [redacted] Scribner, NE[redacted]
Height: [redacted]" *Weight:* [redacted]

Location:	Seat Pos.	Seat Belts:	Air Bags:	
1	3	U	D	*Nature & extent of Injuries:* None

Name: [redacted]
DOB: N/A
Address: [redacted]. Scribner,NE[redacted]
Height: [redacted] *Weight:* 40lbs

Location:	Seat Pos.	Seat Belts:	Air Bags:	
N/A	N/A	N/A	N/A	*Nature & extent of Injuries:* N/A

Name: N/A
DOB: N/A
Address: N/A
Height: N/A *Weight:* N/A

Location:	Seat Pos.	Seat Belts:	Air Bags:	
N/A	N/A	N/A	N/A	*Nature & extent of Injuries:* N/A

DOB:
Address: N/A
Height: N/A

Where, when, and by whom were the injured treated?
N/A

(Legend for Section IV.)

Location:	*1. Incident vehicle 2. Other Vehicle 3. Pedestrian 4. Other*
Seating Position:	 *10. Unknown 11. Other*
Seat Belts Worn:	*U. Unknown L. Lap Only S. Shoulder Only B. L+S belt N. None Worn C. Child Restraint*
Airbag Status:	*NA. Not equipped N. Airbag not deployed D. Airbag deployed*

Incident Investigation Report

V. Other Property Damage

Source of information (unless otherwise noted): N/A

Other vehicle model year, make, model name: N/A

Name, address, phone of other vehicle owner: N/A

Name, address, phone of other vehicle driver: N/A

Nature & extent of other vehicle damage: N/A

Nature & extent of property (other than motor vehicle) damage & name of owner:

N/A

Incident Investigation Report

VI. Investigation Results

Date of vehicle inspection: 3.20.14 *Location of inspection:* NISSAN OF OMAHA

Nature & extent of damages to vehicle & estimated cost of repairs (Attach estimate if available):

N/A

Have you located any related prior repair orders? (Yes/No): NO

Photos taken by: LANCE DAVIS *# photos:* 83

Observations / findings. Be as detailed as possible, put "Not Available" in sections that you are not able to inspect. Include observations and findings from test drives and Consult diagnostics.

- *Exterior / Body:*

No abnormalities found at time of inspection.

- *Engine / Transmission / Drivetrain:*

No abnormalities found at time of inspection

- *Underbody / Suspension / Steering / Wheels & Tires:*

RR tire had low tread (see photo US Quarter used for scale)
No other abnormalities

- *Interior Observations / Seats / Instrument Panel / Headliner / Trim:*

No abnormalities found at time of inspection.

- *Seat Belts / Child Restraints (if applicable):*

Child booster seat found in LR seat. Per probe child seat was unoccupied.

- *Air Bags:*

Passenger side curtain airbag and passenger side airbag both deployed.

- *Additional Observations / Findings (describe any inspection items not covered under headings above, e.g. vehicle test drive with customer, site observations, etc):*

N/A

- *Summary. List factual inspection findings pertaining to each allegation made by claimant. Ensure appropriate IIR supplements are filled out.*

#	*Allegation*	*Factual Findings*
1	Unwarranted airbag deployment	Both side curtain and side airbag were deployed upon inspection.
2	N/A	N/A
3	N/A	N/A
4	N/A	N/A
5	N/A	N/A

Have alleged defective parts been removed from vehicle? (Yes/No):
NO
If yes, by whom? *Present location:* N/A

N/A

Incident Investigation Report

CAR #:
Claimant: [redacted]
VIN: 3N1CN7AP2CL[redacted]

Reporter's Signature: _____

Reporter's Name & Region:

Incident Investigation Report

IIR Supplement: Restraint System Checklist

** On seat belt systems with more than one belt, buckle or retractor, please specify (e.g. Lap or Shoulder).*

DRIVER'S SEAT BELT*

Model #: TI-G625
Mfg. Date: 2011
Lot #: 1223
Manufacturer: TK HOLDINGS INC

AS-FOUND CONDITION*

Fully Stowed? (Yes/No):YES
If extended, measure webbing length from outboard floor anchor to D-ring:N/A
Buckled? (Yes/No):NO

BUCKLE*

Model #: CAH
Buckle latches/unlatches (Yes/No):YES

RETRACTOR*

Retractor(s) spring functioning? (Yes/No): YES
Retractor Locked? (Yes/No): NO
Emergency locking function operable? (Yes/No): YES
Describe how ELR was checked:
VIGOROUSLY PULLED SEVERAL TIMES

RF PASSENGER SEAT BELT*

Model #: TI-G319
Mfg. Date: 2012
Lot #: 2332
Manufacturer: TK HOLDINGS INC

AS-FOUND CONDITION*

Fully Stowed? (Yes/No): YES
If extended, measure webbing length from outboard floor anchor to D-ring:
N/A
Buckled? (Yes/No): NO

BUCKLE*

Model #: CAH
Buckle latches/unlatches (Yes/No): YES

RETRACTOR*

Retractor(s) spring functioning? (Yes/No): YES
Retractor Locked? (Yes/No): NO
Auto locking (ALR) function operable? (Yes/No): YES
Emergency locking function operable? (Yes/No): YES
Describe how ELR was checked:
VIGOROUSLY PULLED SEVERAL TIMES

LR PASSENGER SEAT BELT*

Model #: TI-G625
Mfg. Date: 2011
Lot #: 1224
Manufacturer: TK-HOLDINGS

AS-FOUND CONDITION*

Fully Stowed? (Yes/No):YES
If extended, measure webbing length from outboard floor anchor to D-ring:
N/A
Buckled? (Yes/No):NO

BUCKLE*

Model #: CAH
Buckle latches/unlatches (Yes/No):YES

RETRACTOR*

Retractor(s) spring functioning? (Yes/No): YES
Retractor Locked? (Yes/No): NO
Auto locking (ALR) function operable? (Yes/No): YES
Emergency locking function operable? (Yes/No): YES
Describe how ELR was checked:
VIGOROUSLY PULLED SEVERAL TIMES

RR PASSENGER SEAT BELT*

Model #:N/A N/A
Mfg. Date: N/A
Lot #: N/A
Manufacturer: N/A

AS-FOUND CONDITION*

Fully Stowed? (Yes/No): N/A
If extended, measure webbing length from outboard floor anchor to D-ring: N/A
Buckled? (Yes/No): N/A

BUCKLE*

Model #: N/A
Buckle latches/unlatches (Yes/No): N/A

RETRACTOR(S)*

Retractor(s) spring functioning? (Yes/No): N/A
Retractor Locked? (Yes/No): N/A
Auto locking (ALR) function operable? (Yes/No): N/A
Emergency locking function operable? (Yes/No): N/A
Describe how ELR was checked:
N/A

Incident Investigation Report

IIR Supplement: Restraint System Checklist (continued)

CENTER REAR PASSENGER SEAT BELT*		BUCKLE*	
Model #:	N/A	*Model #:*	N/A
Mfg. Date:	N/A	*Buckle latches/unlatches (Yes/No):*	N/A
Lot #:	N/A		
Manufacturer:	N/A		
*AS-FOUND CONDITION**		RETRACTOR*	
Fully Stowed? (Yes/No):	NA	*Retractor(s) spring functioning? (Yes/No):*	N/A
If extended, measure webbing length from outboard floor anchor to D-ring:	N/A	*Retractor Locked? (Yes/No):*	N/A
		Auto locking (ALR) function operable? (Yes/No):	N/A
Buckled? (Yes/No):	N/A	*Emergency locking function operable? (Yes/No):*	N/A
		Describe how ELR was checked:	N/A

If more than 5 passengers, please add additional information here:

N/A

Child Restraint Observations (if applicable):

Child booster seat in LR seat. Per IIR probe seat was unoccupied at time of incident.

AIRBAG DEPLOYMENT INFORMATION

Driver "front" airbag deployed? (Yes/No):	NO	*RF pass "front" airbag deployed? (Yes/No):*	NO
Driver "side" airbag deployed? (Yes/No/NA):	NO	*RF pass "side" airbag deployed? (Yes/No/NA):*	YES
Left curtain airbag deployed? (Yes/No/NA):	NO	*Right curtain airbag deployed? (Yes/No/NA):*	YES

Airbag Warning Lamp Status *(when ignition is turned ON):*

	Illuminates for approximately 7 seconds and goes off (normal)
	Does not illuminate at all
	Remains illuminated continuously
X	*Flashes continuously*

Consult or CDR Data Included in Report (Yes/No)

Consult DTCs (all items in sub-menus below)	X
○ Current DTCs	X
○ Past DTCs	X
○ Trouble Diag Record	X
Consult Hexadecimal data	X
Consult EDR data (all items in sub-menus below)	X
○ All High-frequency data	X
○ All Low-frequency data	X
○ All Static Data	X
OR	
CDR data (includes DTCs, EDR, and hex data)	X

Always use diagnostic tool appropriate for vehicle. Photograph or scan Consult-II printout since thermal paper will degrade over time.

If any Consult or CDR data above is marked as "No", please explain here why not included in report:

Incident Investigation Report

IIR Supplement: Restraint System Photograph Checklist

VIN plate (door jam)
Odometer
8 external views
Windshield (from standing in front of hood)
Exterior damage close-ups
Underbody views
(if possible and accident circumstances dictate)
Overhead view (if possible)
Engine compartment (hood open)
Engine compartment close-ups (hood open)
Front airbag sensors (where applicable)
Driver side open door view (angled forward)
Driver seat position
(perpendicular view documenting initial position)
Overview of drivers seating area (downward view)
Driver knee bolster area
Driver side upper instrument panel
Header and visor area
Headliner over driver and passenger seating area
Driver "front" airbag overall
Close-ups of any marks on driver "front" airbag
Driver "front" airbag deployment door (upper)
Driver "front" airbag deployment door (lower)
Steering wheel rim side view
Passenger side open door view (angled forward)
RF seat position
(perpendicular view documenting initial position)
Overview of RF seating area (downward view)
RF knee bolster area
RF upper instrument panel
RF passenger "front" airbag overall
Close-ups of any marks on RF pass. "front" airbag
RF passenger "front" airbag deployment door
Driver "side" airbag
RF passenger "side" airbag
Left curtain airbag
Right curtain airbag

Drivers seatbelt - seatbelt label(s)
Drivers seatbelt - overall
Drivers seatbelt - webbing (any marks-note location)
Drivers seatbelt - latchplate metal (both sides)
Drivers seatbelt - latchplate pass thru (both sides)

Drivers seatbelt - pillar guide loop (D-ring)

RF seatbelt - seatbelt label(s)
RF seatbelt - overall
RF seatbelt - webbing (any marks-note location)
RF seatbelt - latch plate metal (both sides)
RF seatbelt - latchplate pass through (both sides)
RF seatbelt - pillar guide loop (D-ring)
RF seatbelt - buckle (side view-inboard & outboard)
RF seatbelt - buckle (end view)


CASE BY CASE BASIS

LR seatbelt - seatbelt label(s)
LR seatbelt - overall
LR seatbelt - webbing (any marks-note location)
LR seatbelt - latchplate metal (both sides)
LR seatbelt - latchplate pass through (both sides)
LR seatbelt - pillar guide loop (D-ring)
LR seatbelt - buckle (side view-inboard & outboard)
LR seatbelt - buckle (end view)
CR seatbelt - seatbelt label(s)
CR seatbelt - overall
CR seatbelt - webbing (any marks-note location)
CR seatbelt - latchplate metal (both sides)
CR seatbelt - latchplate pass through (both sides)
CR seatbelt - buckle (side view-inboard & outboard)
CR seatbelt - buckle (end view)
RR seatbelt - seatbelt label(s)
RR seatbelt - overall
RR seatbelt - webbing (any marks-note location)
RR seatbelt - latchplate metal (both sides)
RR seatbelt - latchplate pass through (both sides)
RR seatbelt - pillar guide loop (D-ring)
RR seatbelt - buckle (side view-inboard & outboard)
RR seatbelt - buckle (end view)
Any visible prior damage (unrelated to subject accident)
Prior repairs to vehicle
Extrication/towing damage
Any non-OEM components (accessories, etc.)
Center console SRS diagnostic module (if necessary)

Incident Investigation Report

Driver seatbelt - buckle (side view-inboard & outboard)
Drivers seatbelt - buckle (end view)

Incident Investigation Report


MANUFACTURED BY NISSAN MOTOR CO., LTD.
DATE: 09/11. GVWR: 3388 LBS
GAWR FR: 1750 LBS GAWR RR: 1671 LBS
THIS VEHICLE CONFORMS TO ALL APPLICABLE FEDERAL MOTOR VEHICLE SAFETY, BUMPER AND THEFT PREVENTION STANDARDS IN EFFECT ON THE DATE OF MANUFACTURE SHOWN ABOVE.
SEE OWNER'S MANUAL FOR ADDITIONAL INFORMATION.
VIN: 3N1CN7AP2CL[redacted] PASSENGER CAR.
COLOR TRIM TRANS AXLE ENGINE
K23 G REOF11A GM38 HR16DE 1598 CC
MODEL: BDTALAZ-EUA 4Z000
3N1CN7AP2CL[redacted]


120
140
ODO
71344
1
1/2
0




348


NISSAN


348








VERSA




348






OK


NISSAN




PELIGRO / VENENO
PERIGO / VENENO
DANGER/POISON


WARNING
AVERTISSEMENT
CAUTION / ATTENTION


A6


A6









thank you
for serve you

OFF
KEY TAG
The Protector
T.M








NISSAN
SRS
AIRBAG






VERSA




















NISSAN
SEAT BELT FOR AUTOMOBILES
MEETS/CUMPLE:
MVSS NO.209, NO.302
HECHO EN MEXICO
MODEL/MODELO: T1-G310
MFD. DATE/FECHA: 2011
LOT NO/LOTE: 1223 A
FABRICANTE :/
MANUFACTURED BY:
TK HOLDINGS INC.
PRE




4T1307








4T1307








PRESS




NISSAN
SEAT BELT FOR AUTOMOBILES
MEETS/CUMPLE
MVSS NO.208, NO.302
HECHO EN MEXICO
MODEL/MODELO: TI-G319
MFD. DATE/FECHA: 2012
LOT NO/LOTE: 2332 A
FABRICANTE :/
MANUFACTURED BY:
TK HOLDINGS INC.
PRE




ET2810








4
ET2810




PRESS


PRESS




HECHO EN MEXICO
MODEL/MODELO: 2011
MFD. DATE/FECHA: 1224
LOT NO/LOTE:
FABRICANTE:
EQUIPO AUTOMOTRIZ AMERICANA
MANUFACTURED BY:
TK HOLDINGS INC.






3X1708






PRESS
















LIBERTY
UNITED STATES OF AMERICA