Technical Bulletin

SERVICE BULLETIN

Classification:	Reference:	Date:
EL15-022	NTB15-076	August 24, 2015

2012-2013 ROGUE;
AROUND VIEW™ MONITOR DTCs SERVICE INFORMATION

APPLIED VEHICLE: 2012-2013 Rogue **(S35)** with Around View™ Monitor system

SERVICE INFORMATION

When performing diagnosis on an applied vehicle with CONSULT-III plus (C-III plus) and opening **Diagnosis (All Systems)**, four Around View™ Monitor (AVM) related DTCs may show as "CURRENT". These DTCs are:

- U111A – Rear Camera Image Signal
- U111B – Side Camera RH Image Signal
- U111C – Front Camera Image Signal
- U111D – Side Camera LH Image Signal

  ➢ Also see page 2 for C-III plus screen showing these DTCs.

NOTE: As of the date of publication of this bulletin, these DTCs are not listed in the 2012 or 2013 Rogue Electronic Service Manuals (ESM). The ESMs will be updated at a later date.

Before Selecting Diagnosis (All Systems):
- The CAMERA button needs to be pressed, or
- The view from the camera(s) need to be seen on the A/V screen.

If the above step is **not** performed:
- The four AVM related DTCs may set and display as "CURRENT".
- The four AVM related DTCs may be found during routine diagnosis (for other issues). If that should occur, these DTCs are erroneous and are to be ignored and erased.

If the four AVM related DTCs are erroneously stored:
- There will be no related symptoms, error messages, warning lights, or any other indications that the AVM system has a malfunction.
- Do not replace any parts.
- Erase the code(s), perform the **Before Selecting Diagnosis (All Systems)** step above, and then recheck for codes.

Example of AVM related DTCs found when diagnosing
another system or simply checking for any DTCs

All DTC	CAN Diag	CAN DIAG SUPPORT MNTR	SRT & P-DTC

Result / **Detailed Information**

BCM

	CRNT
BCM	CRNT
AVM	CRNT
ENGINE	NO DTC
ABS	NO DTC
METER/M&A	NO DTC
AIR BAG	NO DTC
TRANSMISSION	NO DTC

BCM

			DTC Expla

AVM

U111A	REAR CAMERA IMAGE SIGNAL	CRNT	FFD	DTC Expla
U111B	SIDE CAMERA RH IMAGE SIGNAL	CRNT	FFD	DTC Expla
U111C	FRONT CAMERA IMAGE SIGNAL	CRNT	FFD	DTC Expla
U111D	SIDE CAMERA LH IMAGE SIGNAL	CRNT	FFD	DTC Expla

Print for Customer

Print

Save

NTB15-076