Case Number: S2123000001

Release Date: 01/06/2021

Symptom/Vehicle Issue: Rear Wheel Spat Has A Gap Or Appears Loose

Discussion: Review Fig 1 for the condition. If the rear wheel opening spat has a gap or appears loose follow the below instruction.

Fig 1 Wheel spat location. Item 11

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found

Figure 2. Gap measuring.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found

Use a file and remove material as seen in figure 3

Figure 3. Wheel Spat inside surface filed down

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found