Bulletin #: C32-0122-0606	☐ Take Note ☒ Take Action
☐ Retail Operator ☐ Sales Pre-Owned	☐ Business Manager ☒ Parts & Accessories
☐ General Manager ☐ Sales New Car	☐ Service ☐ Administration
Name: Kenny Inoa	Phone Number: 201-571-5623
Title: Material Flow & Inventory Integrity	Source: Parts Logistics
Date: January 25, 2022	Supersedes:

The Ultimate Driving Machine®

BMW PARTS BULLETIN

TEC379 GEARSHIFT STEPTRONIC RETURN

TAKE ACTION

BMW AG has requested the inspection and return of the following part numbers:

25 16 8 483 098 25 16 8 483 099


Stock should not be sold or installed on any vehicle.

Concerned are all parts delivered and shipped so far containing rope pull end piece not crimped. Parts with crimped end piece are ok for use. Pease view images below.


Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC379 must appear in the text of your TEC claim.


TEC379 is valid from January 25, 2022, through February 08, 2022. The deadline for filing a claim under TEC379 is February 08, 2022. All parts must be returned to your facing RDC no later than February 22, 2022.

Please reorder the same part number if needed.



© 2022 BMW of North America, LLC. The contents of this document are confidential and should not be shared with third parties for distribution.







© 2022 BMW of North America, LLC. The contents of this document are confidential and should not be shared with third parties for distribution.