Rear Corner Molding Sealant

Bulletin Type:	TSB	**Publication Date:**	August 2022
Bulletin #(s):	22-072	**Make(s):**	Jayco
Job Code(s):	9801579	**Model(s):**	North Point (382FLRB) North Point (377RLBH)
Flat Rate(s):	.10 Inspection .50 Inspection and Repair	**Model Year(s):**	2022-2023

Incident:	**Missing sealant on rear corner moldings**
Affected Units:	**2022-2023 Jayco North Point**
Parts Kit: None	Parts Kit #: None
Misc. Tools & Supplies:	Caulk Gun Soapy Water Sealant, Geocell 2300 VBS (Jayco Part #0327810) (Purchase Locally)
Parts Return Information:	N/A

REAR CORNER MOLDING INSPECTION

- Determine whether rear corner moldings and rear corner caps for door side and off-door side have been sealed. Please follow the repair below if the corner caps and corner moldings have not been sealed.

REAR CORNER MOLDING REPAIR INSTRUCTIONS

1. Begin by sealing the door side and off-door side moldings on both sides from the top corner cap to the bottom corner cap. The corner caps should already be sealed. The green arrows shown in Figures 1 and 4 show the sides on the unit that need to be sealed.



Fig 1






Fig 2


Fig 3



Fig 4


Fig 5

Jayco's sole obligation under our limited warranty is to repair or replace defective materials and/or workmanship deemed our responsibility as determined by Jayco in our sole discretion. Jayco reserves the right to use new and/or remanufactured parts or materials of similar quality to complete any work, and to make parts and/or design changes as appropriate without notice to anyone. Jayco designs and/or materials changes are done without obligation to incorporate such changes in previously manufactured product. Jayco makes every reasonable effort to ensure field remedies will not adversely affect performance and/or safety of the unit. This field remedy is not intended to extend to future performance of this RV, or any of its materials, components or parts beyond the standard warranty period. The RV owner's obligation to notify Jayco, or one of its independent, authorized dealers, of a claimed defect does not modify any obligation placed on the RV owner to contact Jayco directly when attempting to pursue remedies under state or federal law.

903 South Main Street • P.O. Box 460 • Middlebury, IN 46540