Published
Request ID: 92697

Message

Target

Options

Approve / Deny

Clone

Edit Request

Close

Communication

Publish Dates

- *The Start Date is when the communication will be visible to dealers in DCMail.*
- *The End Date is when the communication will no longer be visible to dealers in DCMail.*
- *NOTE: End Dates are limited to one (1) year from the Start Date. If you wish to lengthen the End Date, you may extend it at any time after publish.*

Start Date 8/17/2023 7:00 AM

End Date 9/7/2023 11:55 PM

Note: All times are **EST**

Extend End Date

Title

What will display in DCMail for dealers to click on.
TIP:Keep titles short, but specific and eye catching.

BEZEL - INSTRUMENT CLUSTER

Flagged for Reporting Agency

NO

Communication Summary

To increase search capability and visibility of your communication, please provide a brief summary or your message (140 characters max). This will display when dealers hover over your communication.

BEZEL - INSTRUMENT CLUSTER

Message

The body of your communication. Use the formatting toolbar above to format text, insert tables, pictures, and/or hyperlinks.

Click Edit > Attach File to attach documents

IMPORTANT NOTES:

- *Pictures must have unique file names. If you receive an error message when uploading a picture, it means the file name has already been chosen. Simply change your file name and try again.*
- *Communications cannot exceed more than 12MB; this includes images and text, and all attachments.*

You have been identified as either having stock on hand or in transit to your dealership.

Please check and return suspect stock of part number **6PM54TX7AB.** Please refer QIR attachment.

Please return all parts back to your facing depot using **Return Code 02**, before 7th September 2023.

For replacement, place new orders.

Return any open orders in process too. Direct questions regarding returns via email to mopardmail@stellantis.com.

Attachments QIR_English.pdf

File Attachment Information

File Size (MB)	File Name
0.13	QIR_English.pdf


17-August-2023

Quality Inspection Request

BEZEL - INSTRUMENT CLUSTER

Suspect Part Identification

Part Number : 6PM54TX7AB

Correct Part	Suspect Part
	
Good Parts : Parts without Missing paint on the parts/shiny surface are good parts.	**Suspect Parts : Parts with Missing paint on the parts/shiny surface are suspect parts.**