
PEDESTAL WELD
CHORD AROUND
CYLINDER IS 1/2
CORRECT WELD BEAD
WRONG
VILLA INTERNATIONAL
ABTS PEDESTAL ASSEMBLY
100025
-4
1:1
E. SALAS
1/10/2024
17 of 72
REVISIONS