August 9, 2022

Product Change Notice - In-Wall slide-out temporary emergency stop brackets

Dear Valued Customer:


Please be advised Lippert is installing temporary emergency stop brackets on the In-Wall Slide-out racks to provide additional safety measures for installation of the In-wall system.

The stop brackets will be installed on both the left (Fixed) and right (Float) side top racks near the end of the extend travel position by Lippert production prior to shipping the In-Wall systems.

These temporary stop brackets will prevent the room from extending too far and possibly falling out before the OEM's permanent method (fascia and/or their own stop) is installed.

NOTE: Failure to remove these temporary emergency stop brackets before end use could result in the In-Wall Slide-out not extending to its fullest extension or damage to the system itself. This is not designed to be the permanent method of stopping the system on the extend stroke.

The change began around Aug. 2 for Renegade only to start.



If you have any questions, please feel free to call me directly or your LCI representative. We value and appreciate your business and partnership.

Sincerely,

Mason Ogle
VP of RV Sales
Lippert Components, Inc.
c: 574.849.1742
mogle@lci1.com

Frequently Asked Questions:

1. **Will a new part number be required?** No, there is no new part number.
2. **Does the price change for the item?** No, there is no price change.
3. **Is the new part wholly interchangeable with the previous version of the part?** Yes, the slide systems are interchangeable with or without the stop brackets.
4. **Does the customer need to replace inventory?** No, the took place on Aug. 2, for Renegade only to start.