

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY

258

Date Received

13-AUG-2000

 Od_or _____
 rt_dt _____
 od_rt _____
 up_ltr _____

Reference No.

727751

 Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (located at front of windshield or driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1FALP4444SF239361	FORD	MUSTANG	1995	

Purchase Date 01-MAR-1996	Dealer's Name _____	Engine Size (CID/CCL) 3.8L	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No. Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☒ 3-Point Belt ☐ Driver's Side Airbag ☐ Passenger's Side Airbag ☐ Motorcyclist ☐ 2-Point Belt	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☒ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Van ☐ Minivan ☐ Other	Body Style ☒ 2-Door ☐ 4-Door ☐ Station Wagon ☐ Pick Up Truck ☐ Other
--	---	---	--	---	--	---

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 05150021	Part Name(s) ENGINE GASKET IS VALVE COVER	Location ☐ Left ☐ Front ☐ Right ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No. of Failures 1	Date(s) of Failure(s) 01-AUG-2000 Mileage at Failure(s) 600 Vehicle Speed at Failure(s) _____	Failed Part(s) Available? Yes No	NHTSA Previously Contacted? Yes No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

HEAD GASKET LEAKING. TECHNICIAN STATES THIS MODEL ENGINE HAS A PROBLEM WITH "ROTTED" OUT HEAD GASKETS. VEHICLE HAS BEEN SERVICED EVERY 3000 MILES (ALL RECORDS AVAILABLE). SEALS TO THE INNER TIE RODS ON THE RACK & PINION BEGAN LEAKING, NOT SERVICEABLE, NECESSARY TO REPLACE THE RACK ASSY. POWER STEERING FLUID CHANGED YEARLY. ALSO, REAR DIFFERENTIAL ASSY REBUILT UNDER MANUFACTURERS WARRANTY @ ABOUT 35000, DUE TO A "WHINING" NOISE. NOISE RETURNED @ ABOUT 46000, NOW OFF WARRANTY.*AK

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.