

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 258

Date Received

02-OCT-2000

 Od_or _____
 Rt_dt _____
 Od_rt _____
 Up_ltr _____

Reference No.

733180

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Listed at front of windshield or drivers side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1FTSX31F6XED77146	FIRESTONE	STEELTEX	1900	

Purchase Date 01-APR-1999	Dealer's Name _____	Engine Size (CID/CC/L) <u>7.3</u>	☒ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☒ 3-Point Belt ☐ Motorbell ☐ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☐ Rear ☒ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Ult ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☒ Pick Up Truck ☐ Other _____
--	---	--	--	---	--	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 02700000	Part Name(s) TIRES	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failures	Date(s) of Failure(s) <u>08-MAY-2000</u> Mileage at Failure(s) <u>15356</u> Vehicle Speed at Failure(s) <u>70</u>	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured <u>0</u>	Number of Fatalities <u>0</u>	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THE LEFT REAR TIRE BLEW OUT AN APPROX. 3 INCH SECTION OF THE SIDE WALL ON THE OUT SIDE OF THE TIRE. A SECTION STAYED ON THE RIM AND THE INSIDE OF THE TIRE WAS INTACT. THERE WAS NO EVIDENCE OF TREAD SEPARATION ON THE TREAD. THE LOCAL FIRESTONE DEALER INSPECTED THE TIRE AND COULD FIND NO REASON FOR THE FAILURE. THEY REPLACED THE TIRE WITH THE SAME TYPE FOR A PRORATED PRICE OF \$64.78. THE TIRES WERE INSPECTED BY ME BEFORE I LEFT FOR YOSEMITE NATIONAL PARK AND INFLATION AND CONDITION APPEARED OK. THE FAILURE OCCURED APPROX. 35 MILES INTO THE TRIP AT ABOUT 9:30 AM PDT AND THE TEMPERATURE WAS APPROX. 60 TO 70 DEGREES. THE FAILURE OCCURED ON BUSINESS IS80, WESTBOUND, INSIDE LANE. THE PICKUP WAS EMPTY AT THE TIME OF FAILURE, IF I WOULD HAVE BEEN PULLING MY FIFTH WHEEL TRAILER WITH

CONTINUED ON BACK (REVERSE)

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 258

Date Received

02-OCT-2000

 Od_or _____
 Rt_dt _____
 od_rt _____
 up_ltr _____

Reference No.

733180

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Listed at front of windshield or driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1FTSX31F6XED77146	FORD TRUCK	F350	1999	

Purchase Date 01-APR-1999	Dealer's Name _____	Engine Size (CID/CC/L) <u>7.3</u>	☒ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☒ 3-Point Belt ☐ Motorbell ☐ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☐ Rear ☒ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Ult ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☒ Pick Up Truck ☐ Other _____
--	---	--	--	---	--	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 02700000	Part Name(s) TIRES	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failures	Date(s) of Failure(s) <u>08-MAY-2000</u> Mileage at Failure(s) <u>15356</u> Vehicle Speed at Failure(s) <u>70</u>	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured <u>0</u>	Number of Fatalities <u>0</u>	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THE LEFT REAR TIRE BLEW OUT AN APPROX. 3 INCH SECTION OF THE SIDE WALL ON THE OUT SIDE OF THE TIRE. A SECTION STAYED ON THE RIM AND THE INSIDE OF THE TIRE WAS INTACT. THERE WAS NO EVIDENCE OF TREAD SEPARATION ON THE TREAD. THE LOCAL FIRESTONE DEALER INSPECTED THE TIRE AND COULD FIND NO REASON FOR THE FAILURE. THEY REPLACED THE TIRE WITH THE SAME TYPE FOR A PRORATED PRICE OF \$64.78. THE TIRES WERE INSPECTED BY ME BEFORE I LEFT FOR YOSEMITE NATIONAL PARK AND INFLATION AND CONDITION APPEARED OK. THE FAILURE OCCURED APPROX. 35 MILES INTO THE TRIP AT ABOUT 9:30 AM PDT AND THE TEMPERATURE WAS APPROX. 60 TO 70 DEGREES. THE FAILURE OCCURED ON BUSINESS IS80, WESTBOUND, INSIDE LANE. THE PICKUP WAS EMPTY AT THE TIME OF FAILURE, IF I WOULD HAVE BEEN PULLING MY FIFTH WHEEL TRAILER WITH

CONTINUED ON BACK (REVERSE)

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.