



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

09-DEC-2001

Od_or _____
rt_dt _____
od_rt _____
ip_lr _____

Reference No.

755452

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Location at bottom of windshield and driver's side) WBAGH8344YDP12968		Vehicle Make BMW	Vehicle Model 740i	Vehicle Year 2000	Current Odometer Reading
Purchase Date 01-JAN-2000	Dealer's Name _____		Engine Size (CID/CC/L) _____	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection	
☒ New ☐ Used	City _____ State _____ Zip Code _____		No Cylinders _____		
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☒ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____
Body Style ☐ 2-Door ☒ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____					

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 03250000 03273000	Part Name(s) BRAKES:HYDRAULIC:ANTI-SKID SYSTEM BRAKES:HYDRAULIC:DISC:ROTOR:DISC HUB	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure 1	Date(s) of Failure(s) 07-DEC-2001	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No
Mileage at Failure(s) 10002		Vehicle Speed at Failure(s) 30	

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damag	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	--------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WARNING LIGHTS DID NOT APPEAR UNTIL ABOUT 4TH EPISODE OF BRAKE PROBLEM. COMPUTER FOUND IT NECESSARY TO ACTIVATE ABS BECAUSE OF ROTOR FAILURE. DIFFICULT TO STOP. IMMEDIATE REPAIR ACTIVITY INSTITUTED WHEN I TOOK IT TO DEALER, BMW. GOOD DEALER RESPONSE. TOO SOON TO HAVE SUCH FAILURE ON VEHICLE. LITES SHOULD HAVE COME ON FIRST TIME I FELT THE ABS DEPLOYED (@ LOW MPH). *AK

CONTINUE ON BACK SHEET

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.