



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY §20

Date Received

08-AUG-2001

Od_or _____
rt_dt _____
pd_rt _____
rp_lr _____

Reference No.

893842

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Location at bottom of windshield and driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1C3XY66RXLD760194	CHRYSLER	NEW YORKER	1990	

Purchase Date	Dealer's Name _____	Engine Size (CID/CC/L) _____	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☐ New ☒ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type	Antilock Brakes	Restraint System	Cruise Control	Drive Train	Vehicle Type	Body Style
☐ Manual ☐ Automatic	☒ Yes ☐ No	☐ 3-Point Belt ☒ Driverside Airbag ☐ Passengerside Airbag	☒ Yes ☐ No	☐ Front ☐ Rear ☐ 4-Wheel	☐ Car ☐ Van ☐ Minivan ☐ Other _____	☐ Sport Util ☐ Truck ☐ Motorcycle ☐ Other _____

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 08300000	Part Name(s) ELECTRICAL SYSTEM: WIRING	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
-----------------------	---	--	---

No of Failure	Date(s) of Failure(s) 28-JUL-2001 90000	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No
---------------	---	--	--

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☒ No	Fire ☒ Yes ☐ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☒ Yes ☐ No
--	---	--------------------------------	---------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

TWO HOURS AFTER VEHICLE WAS PARKED, A FIRE OCCURRED IN ENGINE COMPARTMENT OF VEHICLE. A MECHANIC STATED THAT WIRING JACKET HAD BURNED, CAUSING THE FIRE. PLEASE PROVIDE ANY ADDITIONAL INFORMATION/ATTACHMENTS.*AK

COPIES OF REPORTS - FREE -

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.