



Stacy L. Balzer  
Director  
Service Engineering Operations  
Ford Customer Service Division

Ford Motor Company  
PO Box 1904  
Dearborn, Michigan 48121

February 12, 2024

**TO:** All U.S. Ford and Lincoln Dealers

**SUBJECT: Advance Notice -- Safety Recall 24S06**  
Certain 2018-2020 Model Year Ford Expedition and Lincoln Navigator Vehicles  
Inadvertent Retractor Pretensioner Deployment

**AFFECTED VEHICLES**

Vehicle	Model Year	Assembly Plant	Build Dates
Ford Expedition	2018	Kentucky	1-Oct-2018 through 16-Oct-2018
Ford Expedition	2019	Kentucky	1-Oct-2018 through 30-Jun-2019
Ford Expedition	2020	Kentucky	12-Apr-2019 through 27-Apr-2019
Lincoln Navigator	2018	Kentucky	1-Oct-2018 through 15-Oct-2018
Lincoln Navigator	2019	Kentucky	1-Oct-2018 through 28-Jun-2019
Lincoln Navigator	2020	Kentucky	9-Apr-2019 through 27-Apr-2019

US population of affected vehicles: 77,515. Affected vehicles are identified in OASIS and FSA VIN Lists.

**REASON FOR THIS SAFETY RECALL**

On some of the affected vehicles, the driver and/or front passenger seatbelt retractor pretensioners may deploy inadvertently while the vehicle's engine is on. Inadvertent deployment of the retractor pretensioner will result in the seatbelt being locked in position and will not retract or extend, which is noticeable to the occupant. While the primary seatbelt locking functions continue to function properly, a seatbelt that does not retract or extend may result in injury in the event of a crash.

**SERVICE ACTION**

DO NOT DEMONSTRATE OR DELIVER any new in-stock vehicles involved in this safety recall. A complete Dealer Bulletin will be provided to dealers later in the second half of 2024, when it is anticipated that parts ordering information and repair instructions will be available to support this safety recall. For new vehicle storage guidelines, refer to EFC13033, Storage Guidelines for New Vehicles.

**IMPORTANT: Dealers should open a Repair Order (RO) only when a full dealer bulletin is published. Opening an RO against an Awareness or Advance Notice will result in warranty rejections against a recall.**

**CUSTOMER NOTIFICATION**

Owners of record will be notified via first-class mail after repair instructions and parts ordering information have been provided to dealers.

**PLEASE NOTE:**

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$27,168 per vehicle. Correct all vehicles in your new vehicle inventory prior to delivery.

**DEALER-OPERATED RENTAL VEHICLES**

The Fixing America's Surface Transportation (FAST) Act law effective June 2016 prohibits a rental company from selling, renting or leasing vehicles subject to a safety or compliance recall. Please consult your legal counsel for legal advice.

**QUESTIONS & ASSISTANCE**

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician System (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Sincerely,

A handwritten signature in black ink that reads "Stacy L. Balzer". The signature is written in a cursive, flowing style.

Stacy L. Balzer