

Safety Defect and Noncompliance Report Guide for Vehicles
PART 573 Defect and Noncompliance Responsibility and Reports¹

On January 14, 2013, Supreme [MFR] decided that a defect which relates to motor vehicle safety exists in the motor vehicles listed below, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 Defect and Noncompliance Responsibility and Reports.

Date this report was prepared: 1/18/13

Furnish the manufacturer's identification code for this recall (if applicable): _____

1. Identify the full corporate name of the fabricating manufacturer of the vehicle being recalled. If the recalled vehicle is imported, provide the name and mailing address of the designated agent as prescribed by 49 U.S.C. §30164.

Supreme Corporation
2581 E. Ketchikan Rd.
Goshen, IN 46528

Identify the corporate official, by name and title, whom the agency should contact with respect to this recall.

Kevin Walker
Engineering Manager

Telephone Number: (574) 642-0811 Fax No.: (574) 642-0812

Name and Title of Person who prepared this report.

Kevin Walker
Engineering Manager

Signed:

Kevin Walker

¹ Each manufacturer must furnish a report, to the Associate Administrator for Enforcement, for each defect or noncompliance condition which relates to motor vehicle safety.

I. Identify the Vehicle Models Involved in the Recall

2. Identify the Vehicles Involved in the Recall, for each make and model or applicable vehicle line (provide illustrations or photographs as necessary to describe the vehicle), provide:

Make(s): _____ Model Years Involved: _____ Model(s): _____

Production Dates: Beginning: _____ Ending: _____

VIN Range: Beginning: _____ Ending: _____

Vehicle Type: _____ Bodystyle: _____

Descriptive information which characterizes/distinguishes the recalled vehicles from those model vehicles not included in the recall:

Make(s): SAND K Model Years Involved: 6 Model(s): Zico Lifts

Production Dates: Beginning: 8/2006 Ending: 9/2012

VIN Range: Beginning: _____ Ending: _____

Vehicle Type: _____ Bodystyle: _____

Descriptive information which characterizes/distinguishes the recalled vehicles from those model vehicles not included in the recall:

Make(s): _____ Model Years Involved: _____ Model(s): _____

Production Dates: Beginning: _____ Ending: _____

VIN Range: Beginning: _____ Ending: _____

Vehicle Type: _____ Bodystyle: _____

Descriptive information which characterizes/distinguishes the recalled vehicles from those model vehicles not included in the recall:

Identify the approximate percentage of the production of all the recalled models manufactured by your company between the inclusive dates of manufacture provided above, that the recalled model population represents. For example, if the recall involved Vehicles equipped with certain items of equipment from January 1, 1996 through April 1, 1997, then what was the percentage of the recalled Vehicles of all Vehicles manufactured during that time period.

1% or less +/-

II. Identify the Recall Population

3. Furnish the total number of vehicles recalled potentially containing the defect or noncompliance.

Model	Year	Number of Vehicles Potentially Involved
Trolley	2006-12	104
Sentinel	"	67
Senator HD	"	217
Senator	"	879
Candidate	"	348
S2	"	187
C2	"	14
President	"	28
Total Number Potentially Affected by the Recall:		14
PS2	"	1858

4. Furnish the approximate percentage of the total number of vehicles estimated to actually contain the defect or noncompliance: 100 %

Identify and describe how the recall population was determined--in particular how the recalled models were selected and the basis for the beginning and final dates of manufacture of the recalled vehicles:

STARTRANS / Supreme Corp. REC'D email FROM STANTON SAUCIER informing us that their records indicated they had (1,889) wheel chair lifts they sold us that were affected by these (attached) supplier data. The IT Dept has been contacted to Query Historic Records to confirm said supplier information.

III. Describe the Defect or Noncompliance

5. Describe the defect or noncompliance. The description should address the nature and physical location of the defect or noncompliance. Illustrations should be provided as appropriate.

Refer to Attached Copy of Letter

Describe the cause(s) of the defect or noncompliance condition.

See Letter from Ricor Corp.

Describe the consequence(s) of the defect or noncompliance condition.

See Letter from Ricor Corp.

Identify any warning which can (a) precede or (b) occur.

ARCH OR SPARK

If the defect or noncompliance is in a component or assembly purchased from a supplier, identify the supplier by corporate name and address.

RICOR CORPORATION
A WABTEC COMPANY
7900 NELSON RD.
PANORAMA CITY, CA 91402

Identify the name and title of the chief executive officer or knowledgeable representative of the supplier:

John DOLBEN

IV. Provide the Chronology in Determining the Defect/Noncompliance

If the recall is for a defect, complete item 6, otherwise item 7.

6. With respect to a defect, furnish a chronological summary (including dates) of all the principle events that were the basis for the determination of the defect. The summary should include, but not be limited to, the number of reports, accidents, injuries, fatalities, and warranty claims.
7. With respect to a noncompliance, identify and provide the test results or other data (in chronological order and including dates) on which the noncompliance was determined.

Reason to Letter, email, Ready Repair
from Tico Corp.

V. Identify the Remedy

8. A description of the manufacturer's program for remedying the defect or noncompliance. This program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of the manufacturer's notification of owners, purchasers and dealers, in accordance with §573.13 of this part. A manufacturer's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by §573.13 that is not in a general reimbursement plan shall be submitted in the manufacturer's report to NHTSA under this section. If a manufacturer submits one or more general reimbursement plans, the manufacturer shall update each plan every two years, in accordance with §573.13. The manufacturer's remedy program and reimbursement plans will be available for inspection by the public at NHTSA headquarters.

Through our records determine a list of
customers via letter contact instructing owners what
to do. (Remedy) The information sent should instruct
the owner to follow the Bulletin Guide lines

9. Furnish a description of the manufacturer's remedy for the defect or noncompliance. Clearly describe the differences between the recall condition and the remedy.

Refer to copy of Ricor Corp. Letter

Clearly describe the distinguishing characteristics of the remedy component/assembly versus the recalled component/assembly.

Refer to copy of Ricor Corp. Letter

Identify and describe how and when the recall condition was corrected in production. If the production remedy was identical to the recall remedy in the field, so state. If the product was discontinued, so state.

Refer to copy of Ricor Corp Letter

VI. Identify the Recall Schedule

10. Furnish a schedule or agenda (with specific dates) for notification to other manufacturers, dealers/retailers, and purchasers. Please, identify any foreseeable problems with implementing the recall.

1/14/13 - Supreme Notified of Defect

1/21/13 - NHTSA Contacted

? - ODI office continues into sent from Supreme

? - DRAFT Letter submitted / approved

? - Starting in FEB/MARCH, 2013 OWNERS will BE CONTACTED

VII. Furnish Recall Communications

11. Furnish a final copy of all notices, bulletins, and other communications that relate directly to the defect or noncompliance and which are sent to more than one manufacturer, distributor, or purchaser. This includes all communications (including both original and follow-up) concerning this recall from the time your company determines the defect or noncompliance condition on, not just the initial notification. *A DRAFT copy of the notification documents should be submitted to this office by Fax (202-366-7882) or by E-Mail to RMD.ODI@dot.gov for review prior to mailing.*

Note that these documents are to be submitted separately from those provided in accordance with Part 579.5 requirements.