



**ACURA**

**AUTOMOBILE DIVISION**

American Honda Motor Co., Inc.  
1919 Torrance Blvd., - P.O. Box 2215  
Torrance, CA 90509-9870

March 2017

RE: 2003-2006 MDX  
NHTSA Recall 16V-344

**IMPORTANT**

- **Your vehicle is included in a safety recall and should have the recall service done as soon as possible.**
- **Any authorized Acura dealer will perform the recall service at no charge to you.**

Dear JOHN Q SAMPLE:

**What is the reason for this notice?**

Our records indicate that a SAFETY RECALL has not been completed on this vehicle; refer to the address card for the affected VIN. In certain 2003-2006 Acura MDX vehicles, the passenger's front airbag inflator could produce excessive internal pressure upon deployment. If an affected airbag deploys, the increased internal pressure may cause the inflator to rupture (break apart). In the event of an inflator rupture, metal fragments could pass through the airbag cushion material possibly causing serious injury or fatality to you or others in the vehicle. A prior rupture like this resulted in serious injury.

**What will Acura do?**

Acura will replace your vehicle's passenger's front airbag inflator **free of charge**. Call any authorized Acura dealer and make an appointment to have your vehicle repaired.

**If you have questions**

If you have any questions about this notice, or you need assistance locating a dealer, contact Acura Client Relations at 1-888-234-2138. You may also find this information at [www.myAcura.com](http://www.myAcura.com).

We apologize for any inconvenience this safety recall may cause you.

Sincerely,

**American Honda Motor Co., Inc.  
Acura Automobile Division**

**NOTICE: If this is a leased vehicle, please forward this notice to the lessee.**

FOR DEALER USE ONLY: REFERENCE SVC BULLETIN #16-028

KA3