



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

October 30, 2017

Mr. Alan Davidovich
On-Highway Safety and Compliance Manager
Caterpillar Inc.
100 N.E. Adams Street
Peoria, IL 61629-7150

NEF-150KS
17V-641

Subject: Tie Rod may Loosen

Dear Mr. Davidovich:

This letter serves to acknowledge Caterpillar Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

CATERPILLAR/CT660/2016

Mfr's Report Date: October 11, 2017

NHTSA Campaign Number: 17V-641

Components:

STEERING:LINKAGES:TIE ROD ASSEMBLY

Potential Number of Units Affected: 4

Problem Description:

Caterpillar Inc. (Caterpillar) is recalling all 2016 Navistar CT660S trucks equipped with certain Spicer D or E series steer axles. The castellated nut on the steer axles may not be properly torqued, allowing the tie rod to loosen.

Consequence:

If the tie rod loosens, it may disconnect from the steering knuckle, causing a complete loss of steering and increasing the risk of a crash.

Remedy:

Caterpillar will notify owners, and dealers will tighten the castellated nut and tie rod, replacing them as necessary, free of charge. The recall is expected to begin December 08, 2017. Owners may contact Caterpillar customer service at 1-309-494-3319.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kelly Schuler who may be reached by phone at (202) 366-5227, or by email at kelly.schuler@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement