

**Recall Quarterly Report****18V-150**

**Manufacturer Name :** Mercedes-Benz USA, LLC.  
**NHTSA Recall No. / MFR Recall No. :** 18V-150 /2018060001  
**Recall Subject :** Incorrect Welding of Backrest Rail and Fittings  
**Owner Notification Beginning Date :** JUL 06, 2018  
**Owner Notification End Date:** JUL 06, 2018



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JUL 25, 2018	2018-3	99	10	0	0

This Document Last Updated : AUG 09, 2018

**Definitions :**

- Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).
- Recall Population :** The total number of products recalled by the manufacturer.
- Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.
- Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.
- Total Removed :** Products that have been scrapped, stolen, or exported.